

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-03824
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-5131
7. Lease Name or Unit Agreement Name EAST HENSHAW UNIT TR. 9
8. Well No. #7
9. Pool name or Wildcat WEST HENSHAW GRB

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator SALADO OPER. L.L.C.	
3. Address of Operator P.O. BOX 1925 HOBBS, N.M. 88241	
4. Well Location Unit Letter J _____ : 3654.5 feet from the NORTH line and 1650' feet from the EAST line Section 2 Township 16S Range 30E NMPM EDDIE County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3937 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: FINAL REPORT PLUGGING AND ABANDONMENT ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

6/01/01 RIGGED UP MAYO MARRS CASING PULLING INC.
6/04/01 RIH WITH 1.25" TUBING AND TAGGED TD AT 2250'.
CALLED TIM GUM. OK. SPOTTED 11 SX CEMENT PLUG AT 2250'.
W.O.C. TAGGED T.O.C. AT 1657'. TESTED CASING TO 500#. RIH AND
PERFORATED CASING AT 1500'. SQUEEZED 65SX CEMENT LEAVING
CASING FULL TO SURFACE. ERECTED DRYHOLE MARKER.
CLEARED AND LEVELED LOCATION.

Post P+H

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Michael Stellyfield* TITLE *Envir. Eng. Spec. I* DATE *8/20/01*

Type or print name

Telephone No.

(This space for State use)

APPROVED BY *Michael Stellyfield* TITLE *Envir. Eng. Spec. I* DATE *8/20/01*
Conditions of approval, if any:

MAYO MARRS CASING PULLING INC.
BOX 863
KERMIT, TEXAS 79745

NEW MEXICO OCD
BID ID # 00-521-25-2004

OPERATOR: SALADO OPERATING LLC.

Lease: EAST HENSHAW UNIT 9-7

Project: P & A – CEMENTING REPORT

6-04-2001 – SPOT 11 SXS @ 2250'-1657' TAGGED

6-04-2001 - PERF. @ 1500' SQUEEZE 65 SXS LEAVE CASING FULL

INSTALL DRY HOLE MARKER

CIRCULATE 10# MUD



MAYO MARRS CASING PULLING INC.
BOX 863 KERMIT, TEXAS 79745

NEW MEXICO OCD

ATTN: TIM GUM

Lease: E. HENSHAW UNIT TRACT 9 # 7

OPERATOR: SALADO OPERATING, L.L. C.

Project: P & A

6-01-01

MOVE RIG TO LOCATION

6-04-01

MIRU - RIH WITH 1 1/4" - TAG TD @ 2250' - CALL TIM GUM - OK - SPOT 11 SACKS CEMENT @ 2250' - POOH - WOC - TAG @ 1657' - TEST CASING TO 500# - RIH & PERFORATE @ 1500' - SQUEEZE 65 SXS LEAVING CASING FULL - RIG DOWN - CUT OFF WELLHEAD - INSTALL DRY HOLE MARKER - LEVEL LOCATION - MOVE OUT

