

3-OCC  
1-File

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

**RECEIVED**  
NEW MEXICO OIL CONSERVATION COMMISSION

JAN 5 1971

**O. C. C.**  
**ARTESIA, OFFICE**

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-6672</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>GETTY OIL COMPANY</b>	8. Farm or Lease Name <b>STATE "AO"</b>
3. Address of Operator <b>P.O. BOX 249, HOBBS, NEW MEXICO 88240</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>R</b> <b>2310</b> FEET FROM THE <b>SOUTH</b> LINE AND <b>1650</b> FEET FROM THE <b>EAST</b> LINE, SECTION <b>2</b> TOWNSHIP <b>16-S</b> RANGE <b>30-E</b> NMPM.	10. Field and Pool, or Wildcat <b>WEST HENSHAW</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3921 D.F.</b>	12. County <b>EDDY</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Pull rods and tubing.**

**Mix 18 Bbls. Mud and pump into well.**

**Rig up wireline unit and set CIBP @ 2975'. Dump 15 Ft. Cement on top with bailer.**

**\* Set <sup>50</sup> 10 Ft. Cement Plug at surface.**

**Erect suitable surface marker, and clean location.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

**ORIGINAL SIGNED BY:**

**C. L. Wade**

SIGNED \_\_\_\_\_ TITLE **AREA SUPERINTENDENT**

DATE **12-31-70**

APPROVED BY **W. C. Gressett** TITLE **OIL AND GAS COMMISSIONER**

DATE **JAN 6 1971**

CONDITIONS OF APPROVAL, IF ANY: **as noted above \***

TCW/WLG/bh