

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

3-NMOCC - Artesia  
1-File

RECEIVED

APR 26 1971

O. C. C.  
ARTESIA, OFFICE

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-6672</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>STATE "AO"</b>
9. Well No. <b>1</b>
10. Field and Pool, or Wildcat <b>HENSHAW WEST</b>
12. County <b>EDDY</b>

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-
2. Name of Operator <b>GETTY OIL COMPANY</b>
3. Address of Operator <b>P. O. Box 249, Hobbs, New Mexico</b>
4. Location of Well UNIT LETTER <b>SL</b> <b>2310</b> FEET FROM THE <b>SOUTH</b> LINE AND <b>1650</b> FEET FROM <b>EAST</b> LINE, SECTION <b>2</b> TOWNSHIP <b>16-S</b> RANGE <b>30-E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>3921 D.F.</b>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-1-71 Pulled rods and tubing. Mixed 18 Bbls. Mud and pumped into well. Set CIBP on wire line @ 2975', dumped 15 ft. cement on top with bailer. Set 50' cement plug at surface.

4-22-71 Erected dry hole marker.

Will submit another C-103 when location cleaned up.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY:

SIGNED **G. L. Wade**

TITLE **Area Superintendent**

DATE **April 23, 1971**

APPROVED BY **W. A. Gressett**

TITLE **Area Superintendent**

DATE **FEB 17 1972**

CONDITIONS OF APPROVAL, IF ANY:

WTC/bh