

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TWO
(Other instructions
reverse side)ICATE*
OR re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-069465

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

West Henshaw Premier
Unit Tract 3

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Henshaw Grayburg West

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 3, T-16-S, R-30-E

12. COUNTY OR PARISH

Eddy New Mexico

1.

OIL WELL ☒ GAS WELL ☐ OTHER

RECEIVED

2. NAME OF OPERATOR

Mobil Oil Corporation

OCT 31 1973

3. ADDRESS OF OPERATOR

Box 633, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

ARTESIA, OFFICE

Unit T 1650 FSL & 330 FWL of Sec. 3, T-16-S, R-30-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3846 DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plug & Abandon subject well as per attached plugging procedures

RECEIVED
OCT 19 1973
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Authorized Agent


DATE 10-17-73

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE



*See Instructions on Reverse Side

Instructions


General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE : 1963-O-485229

907-951



MIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS

Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease and Well No: WEST HENSHAW PREMIER CUNIT - TRAIT 5 #2

Field: WEST HENSHAW

County and State: EDDY - NEW MEXICO

RECOMMENDED PROCEDURE:

1. PULL RODS, PUMP & TBB OUT OF THE HOLE
2. SET 150' CEMENT PLUG FROM 2730' to 2880'
3. CUT OFF & PULL FREE 7" Csg AT 1200' ±
4. CIRCULATE HOLE TO MUD LADEN FLUID
5. SET 100' CEMENT PLUG IN & OUT OF CUT OFF POINT
6. SET 100' CEMENT PLUG FROM 400' to 500'
7. SPOT 10 SN PLUG AT SURFACE
8. REMOVE WELL HEAD & INSTALL MARKER

RECEIVED
OCT 19 1973

U.S. GEOLOGICAL SURVEY
MIDLAND, NEW MEXICO

NOTE: VERBALLY APPROVED BY USES OF ARTESIA

JIM KNAUF

ARA 7/25/73

WEST HENSHAW PREMIER UNIT - TRACT 5 #2
UNIT T, S 3 - T 16S R 30E
EDDY COUNTY - NEW MEXICO

10" CSQ CMTW / 50 SY

@ HH2'

7" CSQ 23" / FT CMTW /
100 SY.

@ 2834'

T.D. 2882
RECEIVED
OCT 19 1973
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

ARA 7/25/73