

SUPPLEMENTAL WELL REPORT

WEST HENSHAW PREMIER UNIT #5-2

WEST HENSHAW PREMIER UNIT #5-2, West Henshaw Fld, Eddy Co, NM.
OBJECTIVE: P&A.

11/4 & 2882 TD.

11/5/73 MI&RU Baber Well Serv DD Unit 11/3/73, POH & LD 2400' junk
2-7/8 tbg, left Guib TA & approx 400' 2-7/8 tbg in hole,
SD for nite, then ran Howco cmt ret on 2-3/8 tbg to 2400,
could not pump in, picked up & spotted 50x Class H cmt on
ret, POH w/ tbg, worked & shot 7" csg @ 1200, pulled up 20',
csg stuck, worked csg w/ jacks, would not come free, pulled
60,000# T on csg, SD for nite.

WEST HENSHAW PREMIER UNIT #5-2, 2882 TD.

11/6/73 Shot 7" csg @ 1034, P & LD 7" csg, ran tbg OE, spotted 100'
cmt plug 984-1084, then spotted 100' cmt plug 400-500, POH
w/ tbg, spotted 10x Class H cmt 0-10', inst'l dry hole marker.
Well P&A 11/5/73. Rel Baber Well Serv 7:00 a.m. 11/6/73.

FINAL REPORT

RECEIVED
NOV 14 1973