	N. M. O. C. C. COPY	Budget Bureau No. 42-R358.4. Approval expires 12-31-60.
Form 9-331a (Feb. 1951)		Land Office Las Cruces
(Feb. 1951)	(SUBMIT IN TRIPLICATE)	Lense No. 069642
50R	UNITED STATES	
10 PT 3 195° (DE	PARTMENT OF THE INTERIOR	RECEIVED
SEP FRANKE	GEOLOGICAL SURVEY	
Jones President		30-015-038 OCT 2.4 1960
		UC1 2.4 1900
SUNDRY NO	TICES AND REPORTS O	N WELLS D. D. D.
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATE	
NOTICE OF INTENTION TO CHANGE PLANS		DTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT		RING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPA	AIR WELL SUBSEQUENT REPORT OF RE-D	RILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZI	E SUBSEQUENT REPORT OF ABAN	NDONMENT
NOTICE OF INTENTION TO PULL OR ALTER C	ASING SUPPLEMENTARY WELL HISTOR	אץ
NOTICE OF INTENTION TO ABANDON WELL		
		l
(INDICATE ABOV	E BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTH	IER DATA)
	Sestenber 16	10.22
		, 19.2.2
SE/4SE/4 Bec. 3 1	$\begin{array}{c c} & & & \\ \hline \hline & & \\ \hline \hline & & \\ \hline & & \\ \hline & & \\ \hline \hline \\ \hline \\$	
(¼ Sec. and Sec. No.)	(Twp.) (Kange) (Meridiau)	im: Mariles
(Field)	(County or Subdivision)	(State or '?erritory)
(State names of and expected depths to objection	DETAILS OF WORK ve sands; show sizes, weights, and lengths of proposed of g points, and all other important proposed work)	casings; indicate mudding jobs, cement-
This test was spulled Sep	tember 1Å, 1959, and drilled to at 260°, and the hole took of	
	, the upper portion of the belo	
in, causing a fishing job		
This hole was impossible	to work with further, so the co	
This hale was impossible	to work with further, so the co stud and skidded the rig 35 [†] de	
This hale was impossible		
This hole was impossible		
This hole was impossible		
This hale was impossible		
This hole was impossible		
This hole was impossible and cellar with rock and		
This hole was impossible and collar with rock and	sand and skidded the rig 35 ⁺ de	
This hole was impossible and collar with rock and	sand and skidded the rig 35 ⁺ de	
This hole was impossible and collar with rock and I understand that this plan of work must re Company	sand and skidded the rig 35 ⁺ de	
This hole was impossible and collar with rock and	sand and skidded the rig 35 ⁺ de	
This hole was impossible and collar with rock and I understand that this plan of work must re Company	eccive approval in writing by the Geological Survey bef	
This hole was impossible and collar with yock and I understand that this plan of work must re Company John R. Trigs Address P. Q. Day 5629	eccive approval in writing by the Geological Survey bef	

GPO 862040

