

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NM OIL CONS COMMISSION

Drawer DD FORM APPROVED
Artesia, NM 88210 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Mack Energy Corporation

3. Address and Telephone No.

P O Box 960 Artesia, NM 88211-0960 (505) 748-1288

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Section 8 T-16-S R-30-E 1980 FSL 1980 FWL

Unit K

5. Lease Designation and Serial No.

NM 04068

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Sivley Federal #3

9. API Well No.

30-015-03873

10. Field and Pool, or Exploratory Area

West Henshaw Grayburg

11. County or Parish, State

Eddy, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

*Per ID-2
7-28-95
P&A*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- Spot 35 sks cement. Plug at 2785'. WOC. Tag cement top of 2701'
- Load hole w/mud.
- Perforate casing at base of salt 1123'. Unable to pump into formation. OKed by BLM, Joe LaRfa to spot plug across perforations. Spot 25 sks cement. Plug at 1173'. WOC Tag cement at 962'.
- Perforate casing at top of salt 535'. Squeeze w/35sks cement. WOC. Did not tag cement plug. Re-squeeze 35 sks cement. WOC Tag cement top of 412'.
- Perforate casing at 60'. Circulate cement to surface between 7" @ 10 3/4 w/85 sks w/85 sks leaving 7" full.
- Job complete 5/22/95

Approved as to plugging of the well bottom.
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed *Jim Deane*

Title

Date

(This space for Federal or State office use)

Orig. Signed by Shannon J. Shaw

PETROLEUM ENGINEER

Approved by

Conditions of approval, if any:

Title

Date

7/10/95