

CSF

UNITED STATES
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other Water injection

2. NAME OF OPERATOR
Kay Jay Oil Co.

3. ADDRESS OF OPERATOR
P.O. Box 3565 Midland, Texas 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
 AT SURFACE: 672' FSL-1980' FEL-Sec.8-T16S-
 AT TOP PROD. INTERVAL: R30E
 AT TOTAL DEPTH:

5. LEASE
NM 0560379

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
Southwest Henshaw Premier Unit

8. FARM OR LEASE NAME

9. WELL NO.
3

10. FIELD OR WILDCAT NAME
West Henshaw Grayburg

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Section 8 - T16S - R30E

12. COUNTY OR PARISH | 13. STATE
Eddy | New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3797' GL

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>		<input checked="" type="checkbox"/>
(other)			

RECEIVED

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

SEP 29 1988

O. C. D.
 ARTESIA, OFFICE

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged and abandoned subject waterflood injection well due to termination of water injection as follows:

1. Set CIBP @ 2650' w/15 sx. cement on top
2. Set 25 sx. cement plug 2110' - 1810' (top of queens)
3. Pumped 75 sx. plugged through hole in 5 1/2" casing @ 1100'. WOC & tagged
4. Perforated 5 1/2" casing @ 533' and spotted 40 sx. plugged WOC & tagged
5. Set 10 sx. surface plug.
6. Installed dry hole marker and restored location.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED T. J. [Signature] TITLE Agent DATE 5/15/85

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 9-21-85

CONDITIONS OF APPROVAL, IF ANY:
 Approved as to plugging of the well.
 Liability under bond is retained until surface restoration is completed.

*Post 10-20
 5-24-85
 P & A*