Form 9-331a (Feb. 1951)	Budget Bureau 42-R358.3. Approval expires 12-31-55.
(SUBMIT IN TRIPLIC	CATE) Land Office
APPROVED UNITED STAT	<b>ES</b> Lease No. 04422
DEPARTMENT OF THE	
GEOLOGICAL SUR	VEY
JOHN A FROST	
SUNDRY NOTICES AND REI	PORTS ON WELLS
	NT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO THE MALE AND	NT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	T REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	NT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	TARY WELL HISTORY
(INDICATE ABOVE BY CHECK MARK NATURE OF REPO	RT, NOTICE, OR OTHER DATA)
	Contembra D
Federal "B" Letse	September 9 , 1927
	<b>11980</b> (c. (E.).
Well No. $6-9$ is located $660$ ft. from [N] line an	Ind area ft. from high line of sec. 9
N=/4 h=/4	N. J. F.
	(Meridian)
(Field) (County or Subdivision)	(State or Territory)
The elevation of the derrick floor above sea level is 3815	ft.
DETAILS OF WOR	RK
(State names of and expected depths to objective sands; show sizes, weights, and ler ing points, and all other important pro	ngths of proposed casings; indicate mudding jobs, cement-
streated to pull 8 5/8", and found it stuck. balance (approximately 2100").	
Jetted heavy mud T.D. 2351' to 2140'. Spotted	25 mails and a mail and
Recovered 5 joints (121.16*) of 10 3/4" surface Set 5 sack plug on top of 10 3/4" stub. Jetted surface plug with 10 sacks.	pipe. Jetted heavy mud 2075 to 12 heavy mud 120' to 10'. Set
(i) sotily the marker is eracted and bocation	
	(1,2,2,2,2,2,2,2,2,2,2,2,2,2,2,2,2,2,2,2
I understand that this plan of work must receive approval in writing by the Geol	logical Survey before operations may be a LL
Company John H. Trigg	
Address F. U. Box 5639	
Address F. U. Box 5639 hoswell, New Mexico	sv / funch lin Trade
Roswell, New Mexico B	By Augh W. Tuchen