IN REPLY REFER TO:



UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

> P. O. Box 187 Artesia, New Mexico

LE LE CONTRALLE ARTENA OFRICE

May 28, 1957

Mr. Tom Boyd 103 South Second Street Artesia, New Mexico

Re: Oil and Gas Lease LC 069313

- **7**2

Dear Sir:

Your "Subsequent Report of Abandenment" dated May 7, 1957, covering your well No. 1-Boyd located (330 feet from south and west lines of) section 10, T. 16 S., R. 30 E., wildcat area, Eddy County, New Mexico, is hereby approved.

Very truly yours,

(Orig. Sgd.) JOHN A. FROST

John A. Frost District Engineer

JAF:mm Inspected by John A. Frost May 23, 1957



## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

and the second second

:

(\*) A set of a set

Form 9-331a		Budget Bureau No. 42-R358.4. Approval expires 12-31-60.
(Feb. 1951)	(SUBMIT IN TRIPLICATE)	Land Office Las Cruces
	UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	Lease No. LC 069313 Unit Tom Boyd Federal No. 1

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT		
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY		
NOTICE OF INTENTION TO ABANDON WELL				
(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)				

				<b>y</b> 7,	19 <b>57</b>
Well No. Boyd 1 is located		from $\begin{bmatrix} N \\ \mathbf{s} \end{bmatrix}$ line and		$\left\{ egin{smallmatrix} {f E} \\ {f W} \end{array}  ight\}$ line of sec.	10
SW 1 SW 1 SW 1 10 (1/2 Sec. and Sec. No.)	16 (Twp.)	<b>30</b> (Range)	I. M. P. M. (Meridian)		
	(***₽.)	Eddy		Mexico	
(Field)	(0	County of Subdivision)	(Sta	te or Territory)	

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

As per our conversation we spotted 20 sax cement plug at bottom of hole (3620) and mudded back to 2475', set wooden bridge plug 2475' and spotted 10 sax cement plug and mudded to 2100' spotted 10 sax cement plug, pulled all of 7", mudded hole back to 1175' spotted 10 sax cement plug, mudded back to 515' set 10 sax cement plug, knocked off 8 5/8" at 397' pulled same, mudded to top, set 5 sax cement plug on surface and set marker and description, cleaned up location.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.				
Company	Ton Boyd			
Address	102 South Second			
	Artesia, Nev Marico	By Lolut & Bourlow		
		Title Agent		

U. S. GOVERNMENT PRINTING OFFICE 16-8437-6