

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN PLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC-063928 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
14-08-001-6453

HENSHAW DEEP UNIT

8. FARM OR LEASE NAME

HENSHAW DEEP UNIT

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

HENSHAW-WOLFCAMP

11. SEC., T., R., M., OR B&K. AND

SURVEY OR AREA
SEC. 13, T-16-S, R-30-E

NMPM

12. COUNTY OR TERRITORY

EDDY

13. STATE

NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

SHELL OIL COMPANY (WESTERN DIVISION)

3. ADDRESS OF OPERATOR

P. O. BOX 1509, MIDLAND, TEXAS 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface660' FSL & 660' FWL (SW/4 SW/4) SECTION 13, T-16-S, R-30-E,
NMPM SURVEY, EDDY COUNTY, NEW MEXICO

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3869' DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

DECEMBER 12 THRU DECEMBER 15, 1966.

1. RAN TUBING, SPOTTED CEMENT PLUG 7700'-7860' (WOLFCAMP PERFORATIONS). 25 SX.
2. SHOT AND PULLED 6755' 4 1/2" CASING.
3. SPOTTED CEMENT PLUGS AS FOLLOWS:
25 SX AT 6755' (TOP OF 4 1/2" CASING STUB).
25 SX 4500'-4600' (TOP OF YESO).
50 SX 3280' (BASE OF SAN ANDRES).
50 SX 3030' (BASE OF 7 5/8" CASING).
10 SX SURFACE.
4. ERECTED PRESCRIBED MARKER.
5. PLUGGED AND ABANDONED DECEMBER 15, 1966.

RECEIVED

JAN 19 1967

O. C. C.
ARTESIA, OFFICERECEIVED
JAN 16 1967
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

Original Signed By
SIGNED R. J. DOUBEKTITLE DIVISION MECHANICAL ENGINEER DATE JANUARY 11, 1967

(This space for Federal or State office use)

APPROVED
CONDITIONS OF APPROVAL, IF ANY:JAN 11 1967
R. L. BECKMAN
ACTING DISTRICT ENGINEER

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

APPROVED