

#1

Bright Fed #1 -
(Formerly Hou #1)This well bore diagrams shows
Plug Back Status as of 2-9-9313 3/8 48#
@ 500', 450SX CTSGreybees
2943-45, 6546, 3001-2, 7-15
Lorington
3094-98, 3110-312410' CMT
C&BP at 3250'9 5/8" 40#
@ 3498, 700SX CTS5 1/2 cut and pulled at 3680
CMT Plug TOC at 3585

CMT Ret. at 4246' SQ2 w/100SX

Fish Bore Tubing, w/ cased & Jms
8822-30, SQ2'D
8850-58, SQ2'D15' cement TOC 8845
C&BP at 8950

Penn 9553-60, 64-70, 70-72

25' cement
Baker Mod. 10 PKR at 11569'

Devonian 11680-96

TOC 11773

5 1/2 15.5/17#
at 11860' 550SX
TOC at 12496 CBL

TOC 11872'

75SX Howco

OHCIOP at 12020'

Bit at 13,010

TD = 13,072