

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SUBMIT IN TRIPL. (Other instructions on reverse side)Form approved.
Budget Bureau No. 42-B1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 963925

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Henshaw Deep Unit

8. FARM OR LEASE NAME

Henshaw Deep Unit

9. WELL NO.

3Y

10. FIELD AND POOL, OR WILDCAT

Henshaw Wolfcamp

11. SEC., T., R., M., OR B.E. AND

S. 24, T16S, R30E,
NMPH

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Shell Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 1509, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.
At surfaceUnit K. 1925' FSL & 1960' FWL of Section
24. T16S R30E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3853 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☒
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☒
☐
☐
☒
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-26-75 to 9-2-75

1. Perforated at 8355, 8356, 8448, 8450, 8452, 8454, 8712, 8713, 8736, 8738, 8746, 8747, 8749, 8750 (14 holes).
2. Acidized 8712-8750 with 1500 gal 20% HCl. Acidized 8448-8454 with 1000 gal 20% HCl. Acidized 8355-8356 with 500 gal 20% HCl.
3. Ran tubing and swab tested.

9-7-75 to 9-29-75

4. Set CIBP at 8550. Set cement retainer at 8255. Found casing leak 5511-5524. Set cement retainer at 5410. Pumped 150 sx Class H cement. Drilled out cement and retainers.
5. Set cement retainer at 8252. Pumped 100 sx Class H cement into perforations 8355-8454. Drilled out cement and CIBP at 8550.
6. Ran 273 jts 2 3/8" tubing, set in Baker pecker at 8624. Swab tested well.
7. Shut in well pending further operations.

18. I hereby certify that the foregoing is true and correct

SIGNED

G. W. Tullos

TITLE

G. W. Tullos

Senior Production Engineer

DATE

11-18-75

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of bailing of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963 O-685229

847-485