		WHEN A	LAN NIM	Oil Cons. Division
Form 3160-5 (June 1990)	DEPARTMENT	ED STATES	611 S	. 1 Store Approved Buden Barca No 10020135. Expires: March 31, 1993
	-	ND MANAGEMENT	C E Lea	Designation and Serial No.
SU Do not use this form Use '	INDRY NOTICES A for proposals to drill "APPLICATION FOR	ND REPORTS ON WELLS or to deepen or recentry to a different PERMIT—" for such proposals	6. If in	dian, Allottee or Tribe Name
				nit or CA, Agreement Designation
Type of Well Oil Gas Well Well Name of Operator	Other	MAR 2 4 199	7 8. Well	8910064530 Name and No.
MERIT ENERG 3. Address and Telephone No.	SY COMPANY		Не 9. АРІ V	enshaw Deep #3-Y
12222 Merit	Dr.,Suite 1500,	Dallas,Tx. 75251 972-701-8	30- 377 10. Field	015-03919 and Pool, or Exploratory Area
4. Location of Well (Footage, Sec. Sec. 24-T16, 1925' FSL &	S-R30E	ption)	Hens 11. Cour	haw Wolfcamp ty or Parish, State
CHECK APP	ROPRIATE BOX(s)	O INDICATE NATURE OF NOTIC		y, ₩
TYPE OF SUBM	APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER I SUBMISSION TYPE OF ACTION			
Notice of Intent		X Abandonment		
Subsequent Repo	on	Recompletion Plugging Back		ange of Plans V Construction 1-Routine Fracturing
X Final Abandonm	ent Notice	Casing Repair Altering Casing Other		ter Shut-Off aversion to Injection
Describe Proposed or Completed (give subsurface locations and	Operations (Clearly state all perti	inent details, and give pertinent dates, including estimated oths for all markers and zones pertinent to this work.)*	(Note: Re Completion	pose Water port results of multiple completion on Well on or Recompletion Report and Log form.)
Un 3/5/97, Mr Merit pumped casing. Casi out. Verbal 3695-515', pu displace -#	r. David Glass g 40 sx Class "H" ing would not te was granted. Ta mp sqz Class "C	nsuccessful. Merit Energy (se. Due to uncontrollable ev ave verbal agreement to set cmt below & 10 sx above ret st. Spoke with Gary Gourley gged cement @ 3695'. Per 515 " behind pipe & leave 50' at surface - Pump 50' surface p h & rip up location fina	a cement reta tainer. Attem on 3/6/97 to p o'Displaced ove and below	unsuccessful. iner @ 4850'. oted to test olug well # mud from sgz holes.
	Approved as to Liability under b	plugging of the well bond.	Port ID-2	RECEIVED
	\$urface readore()	on is completed.	4-5-97 14A	MAR 17 97
-	\mathcal{A}		·	BLM ROSWELL, NM
the state of the s	is the and correct			
I hereby certify that the foregoing Signed	Horen	Title Mgr. Regulatory Afiair	"S Data	3/9/97