

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. N. M. 04393  
Unit Leonard

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 11, 1957

Well No. 1 is located 330 ft. from N line and 330 ft. from W line of sec. 31  
NW/4 NW/4 of Sec. 31 T-16-S R-30-E N. M. P. M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Undesignated Eddy New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3711 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

February 4, 6, 1957: The well was plugged as follows: Tubing was run to Total Depth, and cement was pumped from Total Depth to 2500', Cement plugs placed from 2300' to 2100', 1,000' to 1050', 450' to 500', 25' to surface. Heavy mud laden fluid was placed between all cement plugs. All casing was recovered except 5-1/2" which was left in the hole from 2185' to 2562'. Monument was erected over well site and marked with company name and location. Ground has been leveled and final clean up made.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company DeKalb Agricultural Assn., Inc.  
 Address 306 Lubbock National Bldg.  
Lubbock, Texas  
 By [Signature]  
 Title Production Supt.






(SUBMIT IN TRIPLICATE)

Land Office NM 04393

Lease No. \_\_\_\_\_



DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Unit \_\_\_\_\_

### SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 10, 1956

Well No. 1 Leonard is located 330 ft. from [N] line and 330 ft. from [W] line of sec. 31

N. 1/4 sec. 31 16S 30E N.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Undesignated Eddy New Mexico  
(F.M.D.) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3711 (GL) ft.

#### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We propose to drill with cable tools to a total depth of approximately 2800 ft to the Grayburg formation. Will drill 11" hole to 450', set 8-5/8" surf casing, 32#, cemented with 150 sacks, circulated, set 7" at 2000 ft cement with 100 sacks drill 7-7/8" hole from 450' to total depth and set 5 1/2" casing 11# at approximately 2700', cement with 100 sacks, ~~cannt.~~

No drill stem tests or perforations will be made.

COPY

COPY

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company DeKalb Agricultural Association, Inc.

Address 306 Lubbock National Building

Lubbock, Texas By Jack L. Snow

Title Production Supt.