

NM OIL CONS. COMMISSION  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Drawer DD

SUBMIT IN ONE DATE  
Artesian Instructions on reverse sideForm approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM - 02427

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Water Injection	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR J. Cleo Thompson	8. FARM OR LEASE NAME Etz C WSLD Tr 13
3. ADDRESS OF OPERATOR c/o Oil Reports & Gas Services, Inc. Box 763, Artesia, N.M. 88201	9. WELL NO. 3
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface  660' FSL & 660' FEL of Sec 34	10. FIELD AND POOL, OR WILDCAT Square Lake - G-34
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)
12. COUNTY OR PARISH Eddy	13. STATE NM

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☒(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Work began 4/25/83. Ran bit to 2542 & stopped. Worked bit down to 2720. Hit metal of old packer left in hole at 2720. Unable to recover packer. Pulled bit and set cast iron bridge plug at 2700 & capped with 25 sacks cement. Perforated 4 holes at 1345 & squeezed with 50 sacks cement. Tag top of plug at 1205, estimated 100' cement behind casing. Perforated 4 holes at 535 & squeezed with 50 sacks. Tag top of plug at 305, estimated 100' cement behind casing. Set 50 sack plug at surface. Well plugged and abandoned 4/29/83.

RECEIVED

MAY 11 1983

OIL &amp; GAS

ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*Barbara D. Hales*

TITLE

Agent

DATE

5/9/83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

9-2316

CONDITIONS OF APPROVAL, IF ANY: