

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
ARTESIA, NM 88210

45F
Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Injection		2. NAME OF OPERATOR J. Cleo Thompson	
3. ADDRESS OF OPERATOR P.O. Box 6445 Odessa, Texas 79767		4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL 1980 FEL of Sec. 34	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3740'	
5. LEASE DESIGNATION AND SERIAL NO. N.M. 02427		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME West square Lake Uni		8. FARM OR LEASE NAME Tract 14 EL2 E	
9. WELL NO. 3		10. FIELD AND POOL, OR WILDCAT Square lake	
11. SEC., T., S., M., OR BLK. AND SURVEY OR AREA Sec. 34 T16s R30e		12. COUNTY OR PARISH EDDY	
13. STATE NM			

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Plug & abandon

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- (1) Set C.I.B.P. @2750' w/35' cmt. on top.
- (2) Perf. @2225' could'nt break dwn. Queens and Seven rivers spotted 50 sx. cmt. top of cmt. @ 2070'
- (3) Perf. @ 1200' pumped 25 sx. cmt. Top of cmt. @ 1071' (Base of salt)
- (4) Perf. @450 pumped 176 sx. cmt. to circulate and leave 5½ csg. full
- (5) Cut csg. below ground level and set surface marker.

Witnessed By:
Johnny Robinson
(State Oil Commission)

Post IO-2
5-30-86
P4A

18. I hereby certify that the foregoing is true and correct

SIGNED

Archie L. L. L.

TITLE

Production Foreman

DATE

5-22-86

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE