Form 3160-5 (November 1983) (Formerly 9-331) DEPARTMENT OF THE INTER- BUREAU OF LAND MANAGEMENT	15.15		1 1085
SUNDRY NOTICES AND REPORTS (Do not use this form for proposals to drill or to deepen or plug I Use "APPLICATION FOR PERMIT—" for such p	ON WELLS	6. IF INDIAN, ALLOTTEE O	R TRIBE NAME
OIL GAS WELL OTHER Injection	REŒEIVED BY	7. UNIT AGREEMENT NAME West square	
J. Cleo Thompson 3. ADDRESS OF OPERATOR	APR 27 1987	8. FARM OR LEASE NAME Tract 14 9. WELL NO.	
P.Q. Box 6445 Odessa, Texas 7 1. LOCATION OF WELL (Report location clearly and in accordance with an See also space 17 below.)	O. C. D. 767 ARTESIA, OFFICE	3 10. FIELD AND POOL, OR W	VILDCAT
660' FNI. 1980 FEL of Sec. 34	·	Square lak 11. SEC., T., B., M., OR BLE SURVEY OR ARMA	
14. PERMIT NO. 15. ELEVATIONS (Show whether DF 3740 t	, RT, GR, etc.)	12. COUNTY OR PARISH 1	6s R30e 3. STATE
16. Check Appropriate Box To Indicate N	lature of Notice, Report, or C	<u> </u>	WH
NOTICE OF INTENTION TO:		UENT REPORT OF:	
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL 1Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent proposed work. If well is directionally drilled, give subsurface locationent to this work.) *	t details, and give pertipent dates, tions and measured and true vertica	of multiple completion on	Well
 (1) Set C.I.B.P. @2750' w/35' (2) Perf. @2225' could'nt brea spotted 50 sx. cmt. t (3) Perf. @ 1200' pumped 25 sx (4) Perf. @450 pumped 176 sx. (5) Cut csg. below ground leve 	k dwn. Queens and op of cmt. @ 2070'. cmt. Top of cmt. cmt. to circulate 1 and set surface	' . @ 1071' (Base and leave 55	e of salt) csg. full.
witnesd By Robinson Sohnny Robinson State oil Commis	(60°;2	× /	
State 5		W. Calies	
18. I bereby certify that the foregoing is true and correct			
SIGNED Handrianto /2. TITLE WOO	Luction Towner	DATE 5-22	-86
(This space for Federal or State office use)	M MANAGER		
	RESOURCE AREA	_ DATE <u>424</u>	87