

COPIES RECEIVED		
DISTRIBUTION		
FE	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
LE	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
U.S.G.S.		
LAND OFFICE		
OPERATOR	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

OCT 1 1982

O. C. D.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-2884

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- TA - WIW	7. Unit Agreement Name Square Lake Flood
2. Name of Operator Newmont Oil Company	8. Farm or Lease Name (West) Continental State
3. Address of Operator P. O. Box 1305, Artesia, New Mexico 88210	9. Well No. 1
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 16S RANGE 30E NMPM.	10. Field and Pool, or Wildcat Square Lake IG -SA
15. Elevation (Show whether DF, RT, GR, etc.) 3794' GLM	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The above well was plugged and abandon as follows:

6/8/82...Spotted 50 sack plug @ approx. 3060'
6/9/82...Tagged plug @ 2936. Spotted second 50 sack plug, WOC 4 hrs. Tagged @ 2270', mudded up hole, perf. @ 1270' and squeezed w/50 sack cement @ 400 psi.
6/10/82..Tagged plug @ 1131', mudded up, perf @ 518' and squeezed w/60 sacks cement, SI w/250#.
6/11/82..Bleed well off, tagged plug @ 445', mudded up and set 15 sack plug and dry hole marker @ surface.

Location ready for inspection

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Ernest J. McYonagill* TITLE Area Manager

DATE 9/30/82

APPROVED BY *Randy Brooks*
CONDITIONS OF APPROVAL, IF ANY:

TITLE Geologist

DATE 12/15/82

*Post FD-2
10-8-82
PVA*