December 5, 1963

John H. Trigg P. O. Box 520 Roswell, New Mexico

Re: GOR Tests, North Square Lake Pool.

Dear Sir:

We are in receipt of Form C-116, "Gas-Oil Ratio Test Report" for your well in the North Square Bake Pool. We notice some differences between these test GORs as reported on Form C-116 and on the actual production GORs as calculated from the production reported by you on Commission Form C-115. These differences are as follows:

			Test	Actual	Production GOR
Lease	<u>Well</u>	Location	<u>GOR C-116</u>	Oct.	Sept.
Fed.PV	#3 M	5-16-31	1330	3100	3100

In so far as possible, the GORs reported on Form C-116 should reflect each well's actual production GOR and conversely, the well's actual proportional production GOR should not vary exceedingly from that reported, especially immediately after the annual test period.

We are, therefore, requesting that you furnish this office with any information available as to the cause of the differences previously mentioned, a copy of the recording chart will be most useful. If you have any questions concerning this matter, do not hesitate to call upon me.

Very truly yours,

Lette .2 theoremak

10b), b. Triqe F. J. For 200 Koswell, Des Maxico

Rei Will Boets Harth aquere Leig. Radi

13°8 7480

A ARE LI SCREPT OF FOLD CALLS, "Geraged Rethy Fork Report for Your Well is the North Square Bake root. We notice some differaanses netwert there test Coix of reported on Form Call6 and on the sourced production CORC as relukieted from the production forperted by you on Commitation Fork Call5. These differences are an follows.

PCC actorbord	Landoz			
<u>1992 .</u> COLE	1:40 8033	<u> Alexandres</u> General	and the second s	strui VS bor

IC 20 (ar 38 possible. dis 50% reperced on Form C-1.0 sharkd refaitt east well's saturi production 40% and conversely the well's accest proportional production 60° scould not very exceedingly from that reported, aspecially immediately after the arreal feac pariod.

de are therefore commenties chan you furning this office with any information available as to the cause of the differences previewaly mentioned, a copy of the reserving chart will be what useful - If you have any questions concerning this matter, do not hearers to call upon as.

Very traily yours.

sjemeje 🦾 👉