

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions  
verse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

011599 API # 30-015-04821

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

015F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ converted to producer from injector

2. NAME OF OPERATOR  
Walsh and Watts, Inc.

3. ADDRESS OF OPERATOR  
1111 Seventh Street Wichita Falls, Texas 76301

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface  
Unit letter "D" or 660' from North line & 660' from West line  
of Sec. 8, T16S, R31E of NMPM.

7. UNIT AGREEMENT NAME

North Square Lake Premier

8. FARM OR LEASE NAME Unit

9. WELL NO.

21

10. FIELD AND POOL, OR WILDCAT

Square Lake (G/SA) North

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

D - 08 - 16S - 31E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4016 G.L.

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Convert injector to producer  
(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

XX

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Convert injector to producer. No longer required in waterflood. Well drilled originally by John H. Trigg as the Federal "PV" Well #5-8.

NOTE: 8-5/8" O.D. set at 682' with 100 sacks (Cement circ. to surface)

4-1/2" O.D. set at 3344' with 200 sacks (Cement top at 2180')

1.) Pulled 2-3/8" O.D. tubing with packer.

2.) Re-ran 2-3/8" O.D. tubing with rods and pump.

3.) Set pumping unit and tied up to gathering system. Commenced pumping 10-01-1999.



Post ID-3  
10-22-99  
CONV from WIW  
to prod

18. I hereby certify that the foregoing is true and correct.

SIGNED

Alfred B. Guinn

TITLE

Vice - President

DATE

10/08/1999

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side