

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO. <b>30-015-04831</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>E6418</b>
7. Lease Name or Unit Agreement Name: <b>North East Square Lake</b>
8. Well No. <b>12</b>
9. Pool name or Wildcat <b>NE Square Lake</b>
10. Elevation (Show whether DR, RKB, RT, GR, etc.)

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator  
**Aghorn Operating Inc.**

3. Address of Operator  
**P O Box 12663**

4. Well Location  
Unit Letter **A** : **660** feet from the **North** line and **660** feet from the **East** line  
Section **9** Township **16S** Range **31E** NMPM County **Eddy**

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
MULTIPLE COMPLETION <input type="checkbox"/>	OTHER: TA'd (casing test) <input type="checkbox"/>
OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Well was TA'd in February 2002.

Set CIBP @ 3560', capped w/ 4 sx. class "C" neat cmt. Loaded hole w/ 10# brine. Test csg. to 500 psi. and leaked off to 200 psi. in 10 minutes. Found hole in csg. between 410' and 465'. Received verbal approval from OCD to TA wll by squeeze. Sqz. 50 sx. class "C" neat cmt. under PKR, set @ 278'. SDFN. Pumped 50 sx. class "C" neat cmt under PKR. Well pressured up. SDFN. Released PKR. tagged TOC @ 320' POOH. Loaded hole w/ 10# brine and tested csg. to 590 psi. for 30 minutes. Chart attached. Witnessed by Mr. Bratcher.

Temporary Abandoned Status approved  
until 2-5-07

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Frosty Gilliam TITLE President DATE 6/26/02

Type or print name Frosty Gilliam Telephone No. 915-550-0804  
(This space for State use)

APPROVED BY [Signature] TITLE [Signature] DATE JUL 3 2002

Conditions of approval, if any:

