1		• •					
Form 9-331 (May 1963)		IED ST			ATE*		reau No. 42
		WENT OF TH		K verse side)		EASE DESIGNATI	
		GEOLOGICAL		Copy of	A. 6. 11	026418 Indian, allot	
		TICES AND F					
(Do not use t	Use "APPLIC	CATION FOR PERMI	IT—" for such prope	to a different reservoir. Deals.)			
1. OIL GAS	FT ,			······································	7. 0	NIT AGREEMENT	NAME
WELL WEL 2. NAME OF OPERATO		Vater Inject	ion		-1		
	" L Corporatio	00			N I	theast Sc	•
3. ADDRESS OF OFERS					9. w	Premier L	loit
P. O. Box	(633, Midla	and, Texas	<b>7</b> 9701			10	
4. LOCATION OF WELL See also space 17 At surface	, (Report location below.)	clearly and in accor	rdance with any Sta	ite requirements.*	ຮໍຊີປ	are Lake	Graybur
Unit letter C,	. 660' from	the north 1	ine and 198	O' from the		n Andres. sec., t., B., M., O	
west line of S	Section 10,	T-16-S, R-3	B1-E, Eddy C	ounty, New Mexic		SURVEY OF AR	EA
	-	-				10-16S-	-31E
14. PERMIT NO.		1.5. ELEVATIONS (	(Show whether DF, RT	, GR, etc.)	12. 0	COUNTY OR PARI	
<u> </u>			4199 DF			Eddy	New N
16.	Check A	ppropriate Box 1	To Indicate Nati	ure of Notice, Report,	or Other	Data	
	NOTICE OF INTE		1		BSEQUENT R		
TEST WATER SHU	T-OFF	PULL OR ALTER CAS	SING	WATER SHUT-OFF		REPAIRING	well
FRACTURE TREAT		MULTIPLE COMPLET		FRACTURE TREATMENT		ALTERING	
SHOOT OR ACIDIZE	°	ABANDON*		SHOOTING OR ACIDIZING		ABANDONN	· · · · ·
REPAIR WELL (Other)		CHANGE PLANS		(Other) Convert			
				Trong rectore re		convet and I ca	form )
17. DESCRIBE PROPOSE proposed work. nent to this wor OBJECTIVE: C 4/24/67 MIRU	Convert to W	NIW. 3770 TI Serv SD Uni	b, 3741 PBTI t, ran SP s <sup>-</sup>	(NOTE: Report re Completion or Re etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts.	dates, includ rertical dept 2-3718)	ing estimated d hs for all mark	late of start ers and zon
17. DESCRIBE PROPOSE proposed work. nent to this wor OBJECTIVE: C 4/24/67 MIRU load, ran bit 4/25/67 Ran S	DA&S Well , scraper o , CO from	NIW. 3770 T Serv SD Uni- on 2-3/8 tbg 3722-3728, (	t, ran SP store to 3722, pt 6' in 6 hrs.	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast	dates, includ certical dept -3718) mpted t	ing estimated d hs for all mark	hate of start ers and zone would n
17. DESCRIBE PROPOSE proposed work. nent to this wor OBJECTIVE: C 4/24/67 MIRU load, ran bit	DA&S Well , scraper o , CO from	NIW. 3770 T Serv SD Uni- on 2-3/8 tbg 3722-3728, (	t, ran SP store to 3722, pt 6' in 6 hrs.	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast	dates, includ certical dept -3718) mpted t	ing estimated d hs for all mark	hate of start ers and zone would n
17. DESCRIEE PROPOSE proposed work. nent to this wor OBJECTIVE: C 4/24/67 MIRU load, ran bit 4/25/67 Ran S 101-S tension 4/26/67 Ran 2	DA&S Well DA&S Well scraper o P, CO from pkr on 91 j	NIW, 3770 T Serv SD Uni on 2-3/8 tbg 3722-3728, 0 ts 2-3/8 cer 8 cement line	bubsurface location D, 3741 PBTI t, ran SP s to 3722, pu 6' in 6 hrs, ment lined f ed tbĝ, tota	etails, and give pertinent of s and measured and true v top @ 3717, atte ulled 92 jts. , then ran plast tbg. al 117 jts, set	dates, includ ertical dept -3718) mpted t ic coat pkr © 3	ing estimated d hs for all mark o CO, SP ed Johnst 636 w/13,	would n
<pre>17. DESCRIBE PROPOSE proposed work. nent to this wor OBJECTIVE: C 4/24/67 MIRU load, ran bit 4/25/67 Ran S 101-S tension 4/26/67 Ran 2 tension, insta</pre>	DA&S Well DA&S Well Sonvert to W DA&S Well Sonvert DA&S Well Sonvert SP, CO from pkr on 91 j ST jts 2-3/8 lled inject	NIW, 3770 T Serv SD Uni on 2-3/8 tbg 3722-3728, 0 ts 2-3/8 cer 8 cement line	bubsurface location D, 3741 PBTI t, ran SP s to 3722, pu 6' in 6 hrs, ment lined f ed tbĝ, tota	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast tbg.	dates, includ ertical dept -3718) mpted t ic coat pkr © 3	ing estimated d hs for all mark o CO, SP ed Johnst 636 w/13,	would n
17. DESCRIEE PROPOSE proposed work. nent to this wor OBJECTIVE: C 4/24/67 MIRU load, ran bit 4/25/67 Ran S 101-S tension 4/26/67 Ran 2	DA&S Well DA&S Well Sonvert to W DA&S Well Sonvert DA&S Well Sonvert SP, CO from pkr on 91 j ST jts 2-3/8 lled inject	NIW, 3770 T Serv SD Uni on 2-3/8 tbg 3722-3728, 0 ts 2-3/8 cer 8 cement line	bubsurface location D, 3741 PBTI t, ran SP s to 3722, pu 6' in 6 hrs, ment lined f ed tbĝ, tota	etails, and give pertinent of s and measured and true v top @ 3717, atte ulled 92 jts. , then ran plast tbg. al 117 jts, set	dates, includ ertical dept -3718) mpted t ic coat pkr © 3	ing estimated d hs for all mark o CO, SP ed Johnst 636 w/13,	would n
<pre>17. DESCRIBE PROPOSE proposed work. nent to this wor OBJECTIVE: C 4/24/67 MIRU load, ran bit 4/25/67 Ran S 101-S tension 4/26/67 Ran 2 tension, insta</pre>	DA&S Well DA&S Well Sonvert to W DA&S Well Sonvert DA&S Well Sonvert SP, CO from pkr on 91 j ST jts 2-3/8 lled inject	IW, 3770 The Serv SD Uni- on 2-3/8 tbg 3722-3728, 0 ts 2-3/8 cents cement line ion head, ri	D, 3741 PBTI t, ran SP s to 3722, pu 6' in 6 hrs, ment lined f ed tbĝ, tota ig down & re	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast tbg. al 117 jts, set al DA&S. SD uni	dates, includ ertical dept -3718) mpted t ic coat pkr © 3	ing estimated d hs for all mark o CO, SP ed Johnst 636 w/13,	would n
<pre>17. DESCRIBE PROPOSE proposed work. nent to this wor OBJECTIVE: C 4/24/67 MIRU load, ran bit 4/25/67 Ran S 101-S tension 4/26/67 Ran 2 tension, insta</pre>	DA&S Well DA&S Well Sonvert to W DA&S Well Sonvert DA&S Well Sonvert SP, CO from pkr on 91 j ST jts 2-3/8 lled inject	IW, 3770 The Serv SD Uni- on 2-3/8 tbg 3722-3728, 0 ts 2-3/8 cents cement line ion head, ri	bubsurface location D, 3741 PBTI t, ran SP s to 3722, pu 6' in 6 hrs, ment lined f ed tbĝ, tota	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast tbg. al 117 jts, set al DA&S. SD uni	dates, includ rertical dept =-3718) mpted t ic coat ic coat pkr @ 3 t @ 9:3	o CO, SP ed Johnst 636 w/13, 0 a.m.	would n on Type 000#
<pre>17. DESCRIBE PROPOSE proposed work. nent to this wor OBJECTIVE: C 4/24/67 MIRU load, ran bit 4/25/67 Ran S 101-S tension 4/26/67 Ran 2 tension, insta</pre>	DA&S Well DA&S Well Sonvert to W DA&S Well Sonvert DA&S Well Sonvert SP, CO from pkr on 91 j ST jts 2-3/8 lled inject	IW, 3770 The Serv SD Uni- on 2-3/8 tbg 3722-3728, 0 ts 2-3/8 cen s cement line ion head, ri	D, 3741 PBTI t, ran SP s to 3722, pu 6' in 6 hrs, ment lined f ed tbĝ, tota ig down & re	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast tbg. al 117 jts, set al DA&S. SD uni	dates, includ rertical dept =-3718) mpted t ic coat ic coat pkr @ 3 t @ 9:3	o CO, SP ed Johnst 636 w/13, 0 a.m.	would n on Type 000#
<pre>17. DESCRIBE PROPOSE proposed work. nent to this wor OBJECTIVE: C 4/24/67 MIRU load, ran bit 4/25/67 Ran S 101-S tension 4/26/67 Ran 2 tension, insta</pre>	DA&S Well DA&S Well Sonvert to W DA&S Well Sonvert DA&S Well Sonvert SP, CO from pkr on 91 j ST jts 2-3/8 lled inject	IW, 3770 The Serv SD Uni- on 2-3/8 tbg 3722-3728, 0 ts 2-3/8 cen s cement line ion head, ri	D, 3741 PBT t, ran SP s- to 3722, pu 6' in 6 hrs, ment lined f ed tbĝ, tota ig down & re	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast tbg. al 117 jts, set el DA&S. SD uni	dates, includ rertical dept -3718) mpted t ic coat pkr @ 3 t @ 9:30	o CO, SP ed Johnst 636 w/13, 0 a.m.	would n on Type 000#
<pre>17. DESCRIBE PROPOSE proposed work. nent to this wor OBJECTIVE: C 4/24/67 MIRU load, ran bit 4/25/67 Ran S 101-S tension 4/26/67 Ran 2 tension, insta</pre>	DA&S Well DA&S Well Sonvert to W DA&S Well Sonvert DA&S Well Sonvert SP, CO from pkr on 91 j ST jts 2-3/8 lled inject	IW, 3770 The Serv SD Uni- on 2-3/8 tbg 3722-3728, 0 ts 2-3/8 cen s cement line ion head, ri	D, 3741 PBTI t, ran SP st to 3722, pu 6' in 6 hrs ment lined f ed tbĝ, tota ig down & re <b>RECEI</b> MAY 19	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast tbg. al 117 jts, set al 117 jts, set al DA&S. SD uni <b>VED</b> 1967	dates, includ rertical dept -3718) mpted t ic coat pkr @ 3 t @ 9:30	o CO, SP ed Johnst 636 w/13, 0 a.m.	would n on Type 000#
<pre>17. DESCRIBE PROPOSE proposed work. nent to this wor OBJECTIVE: C 4/24/67 MIRU load, ran bit 4/25/67 Ran S 101-S tension 4/26/67 Ran 2 tension, insta</pre>	DA&S Well DA&S Well Sonvert to W DA&S Well Sonvert DA&S Well Sonvert SP, CO from pkr on 91 j ST jts 2-3/8 lled inject	IW, 3770 The Serv SD Uni- on 2-3/8 tbg 3722-3728, 0 ts 2-3/8 cen s cement line ion head, ri	D, 3741 PBTI t, ran SP st to 3722, pt 6' in 6 hrs, ment lined f ed tbĝ, tota ig down & re <b>R E C E I</b> MAY 1 9	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast tbg. al 117 jts, set al 117 jts, set al DA&S. SD uni VED 1967 C.	dates, includ rertical dept -3718) mpted t ic coat pkr @ 3 t @ 9:30	o CO, SP ed Johnst 636 w/13, 0 a.m.	would n on Type 000#
<pre>17. DESCRIBE PROPOSE proposed work. nent to this wor OBJECTIVE: C 4/24/67 MIRU load, ran bit 4/25/67 Ran S 101-S tension 4/26/67 Ran 2 tension, insta</pre>	DA&S Well DA&S Well Sonvert to W DA&S Well Sonvert DA&S Well Sonvert SP, CO from pkr on 91 j ST jts 2-3/8 lled inject	IW, 3770 The Serv SD Uni- on 2-3/8 tbg 3722-3728, 0 ts 2-3/8 cen s cement line ion head, ri	D, 3741 PBTI t, ran SP st to 3722, pu 6' in 6 hrs ment lined f ed tbĝ, tota ig down & re <b>RECEI</b> MAY 19	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast tbg. al 117 jts, set al 117 jts, set al DA&S. SD uni VED 1967 C.	dates, includ rertical dept -3718) mpted t ic coat pkr @ 3 t @ 9:30	o CO, SP ed Johnst 636 w/13, 0 a.m.	would n on Type 000#
<pre>17. DESCRIBE PROPOSE proposed work. nent to this wor OBJECTIVE: C 4/24/67 MIRU load, ran bit 4/25/67 Ran S 101-S tension 4/26/67 Ran 2 tension, insta Complete as WI</pre>	DA&S Well DA&S Well scraper o P, CO from pkr on 91 j 7 jts 2-3/8 lled inject W.	IW. 3770 The serv SD United give Serv SD United Stress St	D, 3741 PBTI t, ran SP st to 3722, pt 6' in 6 hrs, ment lined f ed tbĝ, tota ig down & re <b>R E C E I</b> MAY 1 9	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast tbg. al 117 jts, set al 117 jts, set al DA&S. SD uni VED 1967 C.	dates, includ rertical dept -3718) mpted t ic coat pkr @ 3 t @ 9:30	o CO, SP ed Johnst 636 w/13, 0 a.m.	would n on Type 000#
<pre>17. DESCRIBE PROPOSE proposed work. nent to this wor OBJECTIVE: C 4/24/67 MIRU load, ran bit 4/25/67 Ran S 101-S tension 4/26/67 Ran 2 tension, insta</pre>	DA&S Well DA&S Well scraper o P, CO from pkr on 91 j 7 jts 2-3/8 lled inject W.	IW. 3770 The serv SD United give Serv SD United Stress St	RECEI MAY 19	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast tbg. al 117 jts, set el DA&S. SD uni VED 1967 C. FFICE	dates, includ rertical dept -3718) mpted t ic coat pkr @ 3 t @ 9:30	o CO, SP ed Johnst 636 w/13, 0 a.m.	would n on Type 000#
<pre>17. DESCRIBE PROPOSE proposed work. nent to this wor OBJECTIVE: C 4/24/67 MIRU load, ran bit 4/25/67 Ran S 101-S tension 4/26/67 Ran 2 tension, insta Complete as WI</pre>	DA&S Well DA&S Well scraper o P, CO from pkr on 91 j 7 jts 2-3/8 lled inject W.	IW. 3770 The serv SD United give Serv SD United Stress St	RECEI MAY 19	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast tbg. al 117 jts, set al 117 jts, set al DA&S. SD uni VED 1967 C.	dates, includ rertical dept -3718) mpted t ic coat pkr @ 3 t @ 9:30	o CO, SP ed Johnst 636 w/13, 0 a.m. EEVE GEOLUSIE RTESIA	would n on Type 000#
17. DESCRIEE PROPOSE proposed work. nent to this wor OBJECTIVE: C 4/24/67 MIRU load, ran bit 4/25/67 Ran S 101-S tension 4/26/67 Ran 2 tension, insta Complete as WI 18. I hereby curtify the SIGNED	DA&S Well DA&S Well scraper o P, CO from pkr on 91 j 7 jts 2-3/8 lled inject W.	IW. 3770 The Serv SD United Structure SD United Structure SD United Structure SD United Structure Structur	D, 3741 PBTI t, ran SP stores of the store o	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast tbg. al 117 jts, set el DA&S. SD uni VED 1967 C. FFICE	dates, includ rertical dept -3718) mpted t ic coat pkr @ 3 t @ 9:30	o CO, SP ed Johnst 636 w/13, 0 a.m. EL 1519F	would n on Type 000#
<ul> <li>17. DESCRIEE PROPOSE proposed work. nent to this wor</li> <li>OBJECTIVE: C</li> <li>4/24/67 MIRU load, ran bit</li> <li>4/25/67 Ran S</li> <li>101-S tension</li> <li>4/26/67 Ran 2</li> <li>tension, insta</li> <li>Complete as WI</li> <li>18. I hereby cartify for</li> <li>SIGNED</li> <li>The state for F</li> </ul>	An the foregoing f	IW. 3770 The Serv SD United Structure SD United Structure SD United Structure SD United Structure Structur	D, 3741 PBTI t, ran SP s- to 3722, pt 6' in 6 hrs, ment lined f ed tbĝ, tota ig down & re RECEI MAY 19	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast tbg. al 117 jts, set el DA&S. SD uni VED 1967 C. FFICE	dates, includ rertical dept -3718) mpted t ic coat pkr @ 3 t @ 9:30	o CO, SP ed Johnst 636 w/13, 0 a.m. 636 w/13, 0 a.m. 636 w/13, 0 a.m. 636 w/13, 0 a.m.	would n on Type 000#
<ul> <li>17. DESCRIEE PROPOSE proposed work. nent to this wor</li> <li>OBJECTIVE: C</li> <li>4/24/67 MIRU load, ran bit</li> <li>4/25/67 Ran S</li> <li>101-S tension</li> <li>4/26/67 Ran 2</li> <li>tension, insta</li> <li>Complete as WI</li> <li>18. I hereby certify to SIGNED</li> <li>18. I hereby certify to SIGNED</li> <li>Thereby certify to SIGNED</li> </ul>	An the foregoing f	IW. 3770 TH Serv SD Uni- on 2-3/8 tbg 3722-3728, 0 ts 2-3/8 cer cement line ion head, ri	D, 3741 PBTI t, ran SP stores of the store o	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast tbg. al 117 jts, set el DA&S. SD uni VED 1967 C. FFICE	dates, includ rertical dept -3718) mpted t ic coat pkr @ 3 t @ 9:30	o CO, SP ed Johnst 636 w/13, 0 a.m. EL 1519F	would n on Type 000#
<ul> <li>17. DESCRIEE PROPOSE proposed work. nent to this wor</li> <li>OBJECTIVE: C</li> <li>4/24/67 MIRU load, ran bit</li> <li>4/25/67 Ran S</li> <li>101-S tension</li> <li>4/26/67 Ran 2</li> <li>tension, insta</li> <li>Complete as WI</li> <li>18. I hereby certify to SIGNED</li> <li>18. I hereby certify to SIGNED</li> <li>Thereby certify to SIGNED</li> </ul>	And the foregoing for the fore	IW. 3770 TH Serv SD Uni- on 2-3/8 tbg 3722-3728, 0 ts 2-3/8 cer cement line ion head, ri	D, 3741 PBTI t, ran SP s- to 3722, pt 6' in 6 hrs, ment lined f ed tbĝ, tota ig down & re RECEI MAY 19	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast tbg. al 117 jts, set el DA&S. SD uni VED 1967 C. FFICE	dates, includ rertical dept -3718) mpted t ic coat pkr @ 3 t @ 9:30	o CO, SP ed Johnst 636 w/13, 0 a.m. 636 w/13, 0 a.m. 636 w/13, 0 a.m. 636 w/13, 0 a.m.	would n on Type 000#
<ul> <li>17. DESCRIEE PROPOSE proposed work. nent to this wor</li> <li>OBJECTIVE: C</li> <li>4/24/67 MIRU load, ran bit</li> <li>4/25/67 Ran S</li> <li>101-S tension</li> <li>4/26/67 Ran 2</li> <li>tension, insta</li> <li>Complete as WI</li> <li>18. I hereby curtify to SIGNED</li> <li>18. I hereby curtify to SIGNED</li> <li>The reference for F</li> </ul>	And the foregoing for the fore	IW. 3770 TH Serv SD Uni- on 2-3/8 tbg 3722-3728, 0 ts 2-3/8 cen cement line ion head, ri lis true and correct	D, 3741 PBTI t, ran SP s- to 3722, pt 6' in 6 hrs, ment lined f ed tbĝ, tota ig down & re RECEI MAY 19	etails, and give pertinent of s and measured and true v D, Premier (3672 top @ 3717, atte ulled 92 jts. , then ran plast tbg. al 117 jts, set al 117 jts, set al DA&S. SD uni VED 1967 C. FFICE	dates, includ rertical dept -3718) mpted t ic coat pkr @ 3 t @ 9:30	o CO, SP ed Johnst 636 w/13, 0 a.m. 636 w/13, 0 a.m. 636 w/13, 0 a.m. 636 w/13, 0 a.m.	would n on Type 000#