

Submit 3 Copies To Appropriate District Office

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED
OCD - ARTESIA
State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.
30-015-87370

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
NM026418

7. Lease Name or Unit Agreement Name:
Northeast Square Lake Unit

8. Well No.
10

9. Pool name or Wildcat
NE Square Lake

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other **Injection**

2. Name of Operator
AGHORN OPERATING, Inc.

3. Address of Operator
P.O. Box 12663 ODESSA, TEXAS 79768

4. Well Location
Unit Letter **C** : **660** feet from the **North** line and **1980** feet from the **WEST** line
Section _____ Township **16 S** Range **31 E** NMPM **Eddy** County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: **temporarily Abandoned** ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Well failed mechanical integrity test.
Killed well w/ 10# brine. Pool w/ injection string and pkr.
Rit w/ RBP and set @ 3900'. Dump 1x sand on plug.
Pump in leak at 1/4 bpm. Spot 5 bbl polymer pill across casing leak @ 881'.
Squeeze polymer into leak @ 1/4 bpm, 500 psi. Flush to 800 ft.
Secure well head. Shut well in. Clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE **Ft. Mally** TITLE **PRESIDENT** DATE **1/30/02**

Type or print name **Frosty G. Miam, Jr.** Telephone No. **915 550 0804**
(This space for State use) DENIED - REFERENCE NMCD RULE 19.15.D.203 AND 19.15.9.705 **Compliance Officer 2-6-02**