

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Copy to SF
Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED APR 20 1976 O. C. C. ARTESIA OFFICE		5. LEASE DESIGNATION AND SERIAL NO. NH 04421 6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Northeast Square Lake, 9. WELL NO. Premier Unit 28 10. FIELD AND POOL, OR WILDCAT Square Lake Grayburg, SA 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 10, T-16-S, R-31-E 12. COUNTY OR PARISH Eddy 13. STATE New Mexico
1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER 2. NAME OF OPERATOR Mobil Oil Corporation 3. ADDRESS OF OPERATOR Box 633, Midland, Texas 79701 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) Unit B, 660' FNL & 1980' FEL, Sec. 10, T-16-S, R-31-E 14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACTURE TREAT	☐	FRACTURE TREATMENT	☐
SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐
REPAIR WELL	☐	(Other)	☐
(Other)	☐		
PULL OR ALTER CASING	☐	REPAIRING WELL	☐
MULTIPLE COMPLETE	☐	ALTERING CASING	☐
ABANDON*	☒	ABANDONMENT*	☐
CHANGE PLANS	☐		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Move in pulling unit and a 2" work string.
2. Set a cast iron bridge plug at approx. 3,540', cap with 100' of neat cement, approx. 15 sacks of neat cement will be required.
3. Load the hole with 9.5 lb/gal mud laden fluid.
3A. Spot a 100' neat cement plug (15 sx) from 1150'-1050' (top of salt).
4. Spot a 100' neat cement plug (15 sacks) from 269' to 169'.
5. Spot a 10' neat cement plug (5 sacks) in the top of the 4 1/2" casing.
6. Clean-up, level, and abandon the location. Erect monument - Location is B, Sec. 10, T 16S, R 37E.

NOTE: 1) Procedure revised by consultation w/Jim Knauf, Artesia USGS.
2) USGS Form 9-331 & Statement of Surface Restoration Intention is to be filed for BLM approval.
3) USGS @ Artesia, 746-4841, is to be notified 24 hours in advance of commencing work.

RECEIVED

MAR - 2 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Christine D. Tucker

TITLE

AUTHORIZED AGENT

DATE

3-1-76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229

847-485

STATEMENT OF SURFACE RESTORATION INTENTION
ATTACHMENT TO USGS FORM 9-331, SUNDRY NOTICE OF INTENT TO ABANDON

Applicable To: Mobil Oil Corporation
P. O. Box 633
Midland, Texas 79701

Lease Name: Northeast Square Lake Premise Unit
Well No: 28
Location: Sec 10, T-16-S, R-31-E, Unit B

This is to advise your office that surface restoration associated with the above described proposed plugging and abandonment will be conducted in accordance with applicable rules and regulations of the United States Geological Survey and the New Mexico Oil Conservation Commission; and in accordance with any existent agreement with the surface landowner, or in a manner arrived at by agreement with the surface landowner.

Such restoration work will include:

Backfilling of all pits and cellar. Levelling or contouring the location site. Clearing the location area of junk.

FORM 9-331 Dated: 3-1-76

RECEIVED

U.S. GEOLOGICAL SURVEY
MIDLAND, TEXAS

WELL WORK RECOMMENDATIONS
Proposals for 11 Reconditioning and Subsurf. Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: N.E. SQUARE LAKE UNIT Well No. 28
Field: N.E. SQUARE LAKE
County: EDDY State: NEW MEXICO

RECOMMENDED PROCEDURE:

1. MOVE IN PULLING UNIT AND A 2" WORK STRING.
2. SET A CAST IRON BRIDGE PLUG AT APPROX 3,540'
CAP WITH 100' OF NEAT CEMENT. APPROX 15 SACKS
OF NEAT CEMENT WILL BE REQUIRED.
3. LOAD THE HOLE WITH 9.5 LB/GAL MUD LADEN FLUID.
3A. Spot a 100' neat cement plug (15 sx) from 1150' - 1050' (Top of salt)
4. SPOT A 100' NEAT CEMENT PLUG (15 SACKS)
FROM 269' TO 169'.
5. SPOT A 10' NEAT CEMENT PLUG (5 SACKS) IN
THE TOP OF THE 4 1/2" CASING.
6. CLEAN-UP, LEVEL, AND ABANDON THE LOCATION.
Erect monument - Location is B, Sec. 10, T16S, R37E

APR 19 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

Note: 1) Procedure revised by consultation w/ Jim Knauf, Artesia USGS.
2) USGS Form 9-331 & Statement of Surface Restoration Intention is to
be filed for BLM approval.
3) USGS @ Artesia, 746-4841, is to be notified 24 hours
in advance of commencing work.

DIAPHRAGMATIC WELL SITE
N.E. SQUARE LAKE UNIT WELL NO. 28
N.E. SQUARE LAKE FIELD
EDDY COUNTY, NEW MEXICO

G.L. Elev. = 4,227'
D.F. Elev. = 4,234'

8 5/8" 36 #/FT CSG
CMTD W/ 125 SX CIR

219'

RECEIVED

APR 19 1976

U. S. GEOLOGICAL SURVEY
ARRESTA, NEW MEXICO

PREMIER PERFORATIONS

3,757 - 3,763' - 6' OA - 15 HOLES

P.B.T.D.

3,770'

4 1/2" - 116 #/FT J55 CSG T.D.
CM W/ 425 SXS, CIR

3,815'