

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLY
(Other instructions
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 026418

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Northeast Square Lake
Premier Unit

8. FARM OR LEASE NAME

9. WELL NO.

19

10. FIELD AND POOL, OR WILDCAT

SQ Lake GB San Andres Nor

11. SEC., T., R., M., OR BLK. AND
SUBDIVISION OR AREA

Sec. 10, T-16-S, R-31-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER Water Injection

RECEIVED

2. NAME OF OPERATOR

Evergreen Resources Inc

JAN - 7 1992

3. ADDRESS OF OPERATOR

1000 Writer SQ 1512 Larimer St. Denver, CO 80202

O. C. D.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.)

At surface

Unit Letter, 1980 from the North line and 660' from the
West line of Section 10, T-16-S, R-31-E, Eddy County, NM.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4167 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

On Dec. 23, 1991, Rig up Rotary Wire Line. Set 4 1/2 CIBP @ 3575'
With dump bailer dumped 35' cement on CIBP @ 3575', RIH with tubing
spotted 9.5# gelled brime mud from 3540' to 900'. Pull tubing to 900'
spot cement plug to surface. Cut off well head install dry hole marker
and cleaned up location. Rigged down.

Above approved by Shannon Shaw of BLM in Carlsbad on 12/22 & 12/23/91.

Approved as to plugback of the well bore.
Liability under bond is retained until
surface restoration is completed.

Part ID-2
6-26-92
PFA

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Consulting Pet. Engineer

DATE 12-24-91

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side