

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION
AUG 21 1974

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

O. C. C.
ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER - <u>Water Injection</u>		5a. Indicate Type of Lease State ☒ Fee ☐
2. Name of Operator <u>Mobil Oil Corporation</u>		5. State Oil & Gas Lease No. <u>E-6418</u>
3. Address of Operator <u>Box 633, Midland, Texas 79701</u>		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>E</u> <u>660</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>North</u> LINE, SECTION <u>11</u> TOWNSHIP <u>16-S</u> RANGE <u>31-E</u> NMPM.		8. Farm or Lease Name <u>Northeast Square Lake</u> <u>Truman Unit</u>
15. Elevation (Show whether DE, RT, GR, etc.) <u>4410 GL</u>		9. Well No. <u>23</u>
10. Field and Pool, or Wildcat <u>Big Horn Lake Shoshone</u> <u>Lower Artesia Unit</u>		12. County <u>Eddy</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set C.I.B.P. at 3950 and Cap it with 40' of Cement
2. Circulate hole to mud laden fluid
3. Cut off 4-1/2 Csg. and pull 3000'
4. Spot 100' Cement plug in and out of cut-off point
5. Spot 100' Cement plug from 1450' to 1550' Coaming salt section
6. Spot 100' Cement plug from 434 to 534
7. Spot 1024 of Cement at surface
8. Cut off Well head and Install Marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Christine C. Tucker

TITLE Production Clerk

DATE 8-19-74

APPROVED BY W. A. Gressett

TITLE OIL AND GAS INSPECTOR

DATE AUG 21 1974

CONDITIONS OF APPROVAL, IF ANY: Notify N.M.O.C.C. in sufficient time to witness

Plugging

7-12-74
10:10 AM. to P+A

ID 4027

8⁵/₈" 484 - wire.

4¹/₂" 4029 - 200 est top 3000

FS 4000-02

set CIBP @ 3950 w/ 40' cement
load hole w/ mud.

Cut & Pull approx. 2500' 4¹/₂"

355X at slab.

355X @ 1450-1550

355X 450-550

105X surface -