

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-01504877
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Injection Well		5. Indicate Type of Lease Federal STATE <input type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Joe Melton Drilling Co., Inc.		6. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 4203 Midland, Texas 79704		7. Lease Name or Unit Agreement Name: NM-04138 Baxter "B"
4. Well Location Unit Letter <u>H</u> : <u>1980</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>East</u> line Section <u>25</u> Township <u>16S</u> Range <u>31E</u> NMPM Eddy County		8. Well No. <u>2</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4197' GR		9. Pool name or Wildcat Grayburg Jackson Queen-S. Andres

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: Correct MIT failure <input checked="" type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Pull Guiberson packer, ran in hole with retrievable bridge plug on 2" tbg. set at 3759' Pressure up to 550#, no bleed off, held 30 minutes. Drop standing valve down tbg. test tbg. to 2500#, no bleed off. Fish out standing valve unseat RBP, shut down.

Pull RBP, RIH with redressed Guiberson packer, set @ 3759.06' circulate hole with packer fluid. Rig up recording pressure gauge, pressured up casing to 340# held for 20 min., no bleed off. Michael Stubblefield of OCD witnessed test & OK. 6/06/00

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Karen O'Connor TITLE Secretary DATE 6/12/00

Type or print name _____ Telephone No. _____
(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any: