Form 9-331 (May 1963)	NITED STATES EPARTMENT OF THE INTE	SUBMIT IN C LICAT S on verse side)	Form approvement Budget Bure 5. LEASE DESIGNATION	au No. 42-R1424.	
	Y NOTICES AND REPORTS		6. IF INDIAN, ALLOTTE		
(Do not use this form Us	a for proposals to drill or to deepen or plu e "APPLICATION FOR PERMIT—" for such	g back to a different reservoir. proposals.)	7. UNIT AGREEMENT N	AMB	
WELL GAS WELL	OTHER WIW		, sent nondemand in		
2. NAME OF OPERATOR NEWMONT OIL COMPANY				8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR			JOHNSON 9. WELL NO.		
P. O. BOX 1305, ARTESIA, NEW MEXICO 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			№ .:7		
			10. FIELD AND POOL, O		
560 '	FSL & 1980 FEL of Sec. 2	8; T-16s; R-31E	SQUARE 11. SEC., T., R., M., OB SURVEY OR AREA	BLK. AND	
				S-31E- NMPM	
14. PERMIT NO.	15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	12. COUNTY OR PARISE		
6.			Eddy	New Mexico	
	Check Appropriate Box To Indicate	,	**	of in the state of the state o	
Г	E OF INTENTION TO:	BBUR	EQUENT REPORT OF:	-	
TEST WATER SHUT-OFF FRACTURE TREAT	PULL OR ALTER CASING MULTIPLE COMPLETE	WATER SHUT-OFF	REPAIRING	-	
SHOOT OR ACIDIZE	ABANDON*	FRACTURE TREATMENT SHOOTING OR ACIDIZING	ALTERING C		
REPAIR WELL	CHANGE PLANS	(Other)			
(Other)	PLETED OPERATIONS (Clearly state all perting directionally deliberations)	Completion or Recor	ilts of multiple completion mpletion Report and Log fo	rm.)	
	Clean out to 3675 GL Treat formation with 10 to injection	00 gallons 15% reg. a	acid and return	wells	
	and the same of th			ាង មេ លិកា ស្រាស់ គឺសា	
,					
		FRECEIVED SEP101968 WESTESIA WEW ME			
		NED.			
	· · · · · · · · · · · · · · · · · · ·	C. Start W. C. C.			
		10/900 SUF	We.	4 1 1	
	,	SEP - WE ONE			
	. **	Cherry Men			
		1. 5. E.S. 3.			
		E. C. West			
				17 m	
		*			
S. I hereby certify that the f		ivision Superintenden	nt DATE 8/29/	/68	
(This space for Federal or	State office use)				
APPROVED TO	TITLE	•	DATE		
CONTRIGUE OF APPROV	VAL, IF ANY:			1 3.2 3	
				The A	
SEP & h. Mi	*See Instruction	s on Reverse Side	3 h 4 4 8	4.32	
-J- 1 // // 25 MIT -25		!!\!\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			