

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
NM OIL COM. SECTION
Artesia, NM 88210

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 056302 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

SQUARE LAKE FLOOD (EAST)

8. FARM OR LEASE NAME

JOHNSON

9. WELL NO.

7

10. FIELD AND POOL, OR WILDCAT

SQUARE LAKE (G.SA)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 28-16S-31E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

SUNDRY NOTICES AND REPORTS ON RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIW - TA MAR 22 1983

2. NAME OF OPERATOR NEWMONT OIL COMPANY O. C. D. ARTESIA, OFFICE

3. ADDRESS OF OPERATOR P. O. BOX 1305 ARTESIA, N.M. 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

560' FSL 1980' FEL of Sec. 28

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, OR, etc.)
3998' GLM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well was plugged and abandon as follows.....

7/8/82....Spotted plug at 3506' w/100 sacks cement. Top of plug 2620'. Perf base of salt 1735' and squeezed w/50 sacks cement.

7/9/82....Tag plug at base of salt 1646'. Perf top of salt 730'. Squeeze w/50 sacks cmt.

7/10/82....Tagged top plug at 593'

15' surface plug.

Put up dry hole markerlocation ready for inspection.

RECEIVED
JAN 17 1983

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

Area Manager

DATE

1/12/83

(This space for Federal or State Use)

APPROVED BY

PETER V. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 18 1983

FOR

JAMES A. GILLHAM*See Instructions on Reverse Side
DISTRICT SUPERVISOR

Posted 2-2-83
2-18-83
P. 2