

45F

Budget Bureau No. 42-R1429.

NEW MEXICO DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Artesia, NM 88210

LC 056302 (b)

AUG 14 1982

NDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals)

O.C.D.

1. ARTESIA, OFFICE ☐ OTHER ☐

2. NAME OF OPERATOR *Yates Pet. Corp.*

3. ADDRESS OF OPERATOR *P. O. BOX 1305 ARTESIA, N.M. 88210*

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

500' FSL 1980' FEL of Sec. 28

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3998' GLM

12. COUNTY OR PARISH *Eddy* 13. STATE *New Mexico*

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well was plugged and abandon as follows.....


7/8/82....Spotted plug at 3506' w/100 sacks cement. Top of plug 2620'. Perf base of salt 1735' and squeezed w/50 sacks cement.

7/9/82....Tag plug at base of salt 1646'. Perf top of salt 730'. Squeeze w/50 sacks cmt.

7/10/82....Tagged top plug at 593'.

1544 surface plug.

Put up dry hole markerlocation ready for inspection.



OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *Ernest J. McLaughlin*

TITLE *Area Manager*

DATE *1/12/83*

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE *8-12-85*