



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON
Governor
Carol Leach
Acting Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

7 February 2002

G P II Energy Inc.
P.O. Box 50682
Midland, Texas 79710

RE: North Square Lake Unit # 22 D-29-16-31 API 30-015-04905 Violation of Rule 201:
Well needs to be properly abandoned.
North Square Lake Unit # 20 B-30-16-31 API 30-015-04936 Violation of Rule 201:
Well needs to be properly abandoned.
North Square Lake Unit # 33 2-30-16-31 API 30-015-20701 Violation of Rule 201:
Well needs to be properly abandoned.
North Square Lake Unit # 111 B-33-16-31 API 30-015-04979 Violation of Rule 201:
Well needs to be properly abandoned.

Dear Sirs:

This second directive is to notify you that these wells are still in violation of Rule 201.

On 29 October, 2001 a letter was sent notifying you on the violation of Rule 201. An inspection on 5 February, 2002 found no action has been taken.

These wells must be brought into compliance on or before 28 February, 2002.

Failure to bring these wells into compliance by the date stated will cause further enforcement. Such enforcement can be an order to Show Cause why the bond should not be forfeited, the well plugged and civil penalties assessed.

Sincerely,

Van Barton
Field Rep. II