		N. M. O.	C. C. COPY			Copy to SI=	
Form 9–331 (May 1963)	L TED ST	ATES	SUBMIT IN TRI	ATE.	Form approve		
	DEPARTMENT OF TH GEOLOGICAL		(Other instructions verse side)	[n re-] =5.	LEASE DESIGNATION	AND SERIAL NO.	
SU	NDRY NOTICES AND I			<u> </u>	NM 01757		
(Do not use th	dis form for proposals to drill or to e Use "APPLICATION FOR PERM	teports on leepen or plug back	to a different reservoir. als.)		,		
OIL WELL XX WELL 2. NAME OF OPERATOR	OTHER		RECEIV	ED <sup>7.</sup>	UNIT AGREEMENT NA	ME.	
NEWMONT OIL COMPANY			JAN 2 4 197		8. FARM OR LEASE NAME GRIER 'A''		
					9. WELL NO.		
4. LOCATION OF WELL (Report location clearly and in accordance with one State way of the					10. FIELD AND POOL, OR WILDCAT		
					<u>Square</u> Lake	w HDCAT	
1980' ESI	and 511' FWL Sec. 3/				SURVEY OR AREA	LK. AND	
					31-16S-31E		
14. PERMIT NO.	15. ELEVATIONS (	Show whether DF, RT,	GR, etc.)	12	COUNTY OR PARISH	13. STATE	
16.					Eddy	New Mexico	
	Check Appropriate Box T	o Indicate Natur	e of Notice, Report	, or Othe	er Data		
TEST WATER SHUT			8	UBSEQUENT	REPORT OF:		
FRACTURE TREAT	-OFF PULL OR ALTER CASI MULTIPLE COMPLETE		WATER SHUT-OFF Fracture treatment	.	REPAIRING W		
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR ACIDIZIN		ALTERING CA ABANDONMEN	1	
REPAIR WELL (Other)	CHANGE PLANS		(Other)	results of m	nultiple completion o	n. Well	
17. DESCRIBE PROPOSED	OR COMPLETED OPERATIONS (Clearly st. If well is directionally drilled, give	ate all pertinent det	Completion of R	ecompletion	i Report and Log form	n.)	
nent to this work.	) +		and measured and true	vertical de	pths for all markers	and zones perti-	
5/3/72 Mov 5/4/72 Pul	ed in well plugging eq	uipment			:		
5/4/72 Pulled 119 5/8" rods and pump 5/5/72 Set 25 sack cement plug in and out of 5 1/2" casing @ 2954".							
570772 Pul	ied Z" tbg.			J @ 295	4' <b>.</b>	• •	
5/8/72 Working 5 1/2" casing with casing jacks. 5/9/72 Working 5 1/2" casing with casing jacks.							
5/9/72 Working 5 1/2" casing with casing jacks. 5/12/72 Shot 5 1/2" casing @ 520', 453', 385', and 302'. Pulled 301' of 5 1/2" casing, mixed mud mudded up bole and set 35							
	ed mad, madded up noie	and set 75	Sack comont ol	11- 0 3/		-	
J/ J/ / L 3110	c 0 5/0" casing @ 125"	. Worked cas	ing fasing n	artad (	a 601	1 60' 8 5/8''	
	ed mud, mudded up hole led hole with mud and s	set marker @	sack cement pl surface with	ug @ ]:	25 <sup>1</sup> .		
plug	gging job.	•		J JACKS		ompleted	
				REC	Part St. Providence		
		( ) A	.3		ENED		
		per 26.	1-	JUL	7 1079		
		FG, Jag	Ų. ;	S. GEOLC	ICICAL DUD.		
/		2	Al	rtesia, i	NEW MEXICO		
18. I hereby (certify that	the foregoing is true and correct						
SIGNED	sex Lidbetter	TITLE _ Divisi	ion Supintender	nt	DATE JULY	5, 1972	
(This space for Fed	aral or State office use)				1410.0	4072	
APPROVED BY CONDITIONS OF A	PROVAL, IF ANY:	TITLE <b>DISTRICI</b>	ENGINEER		JAN 2 3	13/3	
200							
10	*See	Instructions on R	leverse Side				