

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

MAR 20 1975

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-2721</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>State "C"</b>
9. Well No. <b>1</b>
10. Field and Pool, or Wildcat <b>Square Lake</b>
12. County <b>Sandoz</b>

**O. C. C. ARTESIA, OFFICE**

**SUNDRY NOTICES AND REPORTS ON WELLS**

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
**Kennedy Oil Company, Inc.**

3. Address of Operator  
**Box 151 Artesia, New Mexico 88210**

4. Location of Well  
UNIT LETTER **H**, **1980** FEET FROM THE **North** LINE AND **660** FEET FROM  
THE **East** LINE, SECTION **32** TOWNSHIP **16S** RANGE **11E** N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)  
**3944 DF**

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of completion of any proposed work) SEE RULE 1103.

Plugged and abandoned as follows:

9/9/74 Set bridge plug @ 1150' and capped with 35' cement plug.  
9/17/74 Cut 3/4" casing at 772' and pulled same.  
Ran tubing and placed heavy mud to 822'.  
Placed 100' cement plug at 3/4" pipe stub 822-722'.  
Placed 100' cement plug @ top of salt 995'-695' mud between all plugs.  
Placed surface plug, cleaned, cleared & leveled location.  
Placed regulation marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <b>Pres.</b>	DATE <b>3/19/75</b>
APPROVED BY <u>[Signature]</u>	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		

Quoted 1-2-75  
3-21-75