

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED
 NEW MEXICO OIL CONSERVATION COMMISSION
 MAR 20 1975

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

O. C. C.
ARTESIA, OFFICE

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-2721	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Kennedy Oil Company, Inc.		8. Farm or Lease Name State "C"
3. Address of Operator Box 151 Artesia, New Mexico 88210		9. Well No. 3
4. Location of Well UNIT LETTER H 1980 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 32 TOWNSHIP 16S RANGE 31E NMPM.		10. Field and Pool, or Wildcat Square Lake
15. Elevation (Show whether DF, RT, GR, etc.) 3944 DF		12. County Seddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of completion of any proposed work) SEE RULE 1103.

Plugged and abandoned as follows:

9/9/74 Set bridge plug @ 3150' and capped with 35' cement plug.
 9/17/74 Cut 5½" casing at 772' and pulled same.
 Ran tubing and placed heavy mud to 822'.
 Placed 100' cement plug at 5½" pipe stub 822-722'.
 Placed 100' cement plug @ top of salt 595'-695' mud between all plugs.
 Placed surface plug, cleaned, cleared & leveled location.
 Placed regulation marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Lib B. Kennedy* TITLE **Pres.** DATE **3/19/75**

APPROVED BY *Susan McManis* TITLE **SUPERVISOR, DISTRICT II** DATE **JUL 25 1975**

CONDITIONS OF APPROVAL, IF ANY: