

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

RECEIVED NEW MEXICO OIL CONSERVATION COMMISSION

MAR 20 1975

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

**O. C. C.
ARTESIA, OFFICE**

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-2721	
7. Unit Agreement Name	
8. Farm or Lease Name State "C"	
9. Well No. 4	
10. Field and Pool, or Wildcat Square Lake	
12. County Sddy	

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER- **Water Injection Well**

2. Name of Operator
Kennedy Oil Company, Inc.

3. Address of Operator
Box 151 Artesia, New Mexico 88210

4. Location of Well
UNIT LETTER **C** **1980** FEET FROM THE **North** LINE AND **1980** FEET FROM
THE **East** LINE, SECTION **32** TOWNSHIP **16S** RANGE **31E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3920 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of completion for any proposed work) SEE RULE 1103.

Plugged and abandoned as follows:

9/9/74 Set bridge plug at 3150' and capped with 35' cement plug.
9/17/74 Cut 5 1/2" casing at 1000' and pulled same.
 ran tubing and placed heavy mud to 1050'.
 Placed 100' cement plug at 5 1/2" pipe stubs 1050-950'.
 Placed 100' cement plug at top of salt 555-655. mud between all plugs
 Placed surface plug, cleaned, cleared and leveled location.
 Placed regulation marker.

*Quoted I.R. 22
3-21-75*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>[Signature]</i></u>	TITLE Pres.	DATE 3/19/75
APPROVED BY <u><i>[Signature]</i></u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		