

NO. OF COPIES RECEIVED	11
DISTRIBUTION	
SANTA FE	11
FILE	11
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION

SEP 29 1972

O. C. C.  
ARTESIA, OFFICE

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-2721
7. Unit Agreement Name East Square Lake
8. Farm or Lease Name State "R"
9. Well No. 2
10. Field and Pool, or Wildcat Square Lake G. SA.
12. County Eddy

**"SUNDRY NOTICES AND REPORTS ON WELLS"**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
Newmont Oil Company

3. Address of Operator  
P. O. Box 1305, Artesia, New Mexico 88210

4. Location of Well  
UNIT LETTER E, 1620 FEET FROM THE North LINE AND 1020 FEET FROM  
THE West LINE, SECTION 32 TOWNSHIP 16S RANGE 31E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
3897' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐ OTHER ☐ CASING TEST AND CEMENT JOBS ☐

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- We plan to plug this well in the following manner: *9" - 8 1/4" - 580 - 50*  
*4 1/2" - 3386 - 200*
- Set bridge plug at 3,195' and place 25' cement plug on top.
  - Fill hole with 9.5 lb./gal mud.
  - Perforate 3 holes radially at 1565' (approx. 70' below base of salt) and set cement retainer at 1515'. Cement through tbg and retainer with 35 sacks and leave a cement plug in casing from retainer to perforations.
  - \* Perforate 3 holes radially at <sup>610</sup>575' (approx. 30' above top of salt) and set cement retainer at 525'. Cement through tbg and retainer with 100 sacks of cement and leave a cement plug in casing from retainer to perforation. Cement should circulate.
  - Set 10 sack cement plug in top of 5 1/2" casing.
  - Set marker.

We will notify N.M.O.C.C. in sufficient time to witness operations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed By  
SIGNED C. C. Joy TITLE Dist. Supt. DATE 10/2/72

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE OCT 2 1972

CONDITIONS OF APPROVAL, IF ANY:  
*\* as noted above*