

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

AUG 16 1972

O. C. C.

ARTESIA OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Injection	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Newmont Oil Company	5. State Oil & Gas Lease No. B-2721
3. Address of Operator Box 1305, Artesia, New Mexico 88210	7. Unit Agreement Name East Square Lake
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 16S RANGE 31E NMPM.	8. Farm or Lease Name State "R"
	9. Well No. 3
	10. Field and Pool, or Wildcat Square Lake G. SA.
15. Elevation (Show whether DF, RT, GR, etc.) 3919' G.L.	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

We plan to plug this well in the following manner:

- Set 25 sack cement plug in and out of the 5 1/2" casing shoe @ 3255'.
- Knock off 5 1/2" casing at lowest possible free point, mud up hole and set 35 sack cement plug in and out of 5 1/2" casing stub. If more than 1700' of 5 1/2" is pulled set 35 sack cement plug at base of salt @ 1535'.
- Mud up hole and set 35 sack cement plug in and out of 8 1/4" casing shoe @ 597'.
- Knock off 8 1/4" surface casing at lowest possible free point, mud up hole and set marker at surface with a 10 sack cement plug.

We will notify N.M.O.C.C. in sufficient time to witness operations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Therman L. Lutter TITLE Divn. Supt. DATE 8/14/72

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE AUG 21 1972
CONDITIONS OF APPROVAL, IF ANY: as noted