	_		
NO. OF COPIES RECEIVED]		
DISTRIBUTION	NEW MEXICO OIL	CONSERVATION COMMISSION	Form C+104
SANTA FE /		T FOR ALLOWABLE	Supersedes Old C-104 and C-
FILE /-		AND	Effective 1-1-65
U.S.G.S.	AUTHORIZATION TO TE	RANSPORT OIL AND NATURAL G	APFPEIL
LAND OFFICE	AOTHORIZATION TO TI	CANOLOGIC AND WATERING	WEGEIVED
TRANSPORTER GAS		SI	A10.
	-		NOV 4 1966
OPERATOR 4	4		-
PRORATION OFFICE			APTERIOR C.
Newmont Oil Co.			ARTESIA, OFFICE
Address Room 303. First Nati	lonal Bank, ARtesia, N.	M.	
Reason(s) for filing (Check proper box)	Other (Please explain)	
New Well	Change in Transporter of:	Change of operato	or from Mercury Prod. C
Recompletion	Oil Dry	Gas to Newmont Oil Co	10 - 1 - 6 6
Change in Ownership	Casinghead Gas Con	densate	
f change of ownership give name and address of previous owner			
DESCRIPTION OF WELL AND	LEASE Lease No. Well No. Fool	Name, Including Formation	Kind of Lease
Johnson	13	SquareLake	State, Federal or Fee Federa
Location		bquareance	2002.0
Unit Letter H 1370	Feet From The North	Line andFeet From	The East
Line of Section 33 To	wnship 16S Range	31E , NMPM, Eddy	Count
DESIGNATION OF TRANSPOR	TER OF OIL AND NATURAL	GAS	
Name of Authorized Transporter of Oil	or Condensate	Address (Give address to which appro	ved copy of this form is to be sent)
This well is shut in	n		
Name of Authorized Transporter of Ca		Address (Give address to which appro	ved copy of this form is to be sent)
			
** 11 1 11 14	Unit Sec. Twp. Age.	Is gas actually connected? Wh	en
If well produces oil or liquids, give location of tanks.	Unit Sec. Twp. Rge.	is gas actually connected? Wh	en .
give location of tanks.			en
give location of tanks. If this production is commingled wi	ith that from any other lease or poo	ol, give commingling order number:	
give location of tanks. If this production is commingled with the completion of tanks.	ith that from any other lease or poo	ol, give commingling order number:	
give location of tanks. If this production is commingled wi	ith that from any other lease or pool on $-(X)$	ol, give commingling order number:	Plug Back Same Res'v. Diff. Re
give location of tanks. If this production is commingled with the completion of tanks.	ith that from any other lease or poo	ol, give commingling order number:	
give location of tanks. If this production is commingled with the completion of tanks. COMPLETION DATA Designate Type of Completi	ith that from any other lease or pool on $-(X)$ Gas Well Date Compl. Ready to Prod.	ol, give commingling order number: New Well Workover Deepen Total Depth	Plug Back Same Resty. Diff. Re
give location of tanks. If this production is commingled with the completion of tanks. COMPLETION DATA Designate Type of Completi	ith that from any other lease or pool on $-(X)$ Gas Well Date Compl. Ready to Prod.	ol, give commingling order number:	Plug Back Same Res'v. Diff. Re
give location of tanks. If this production is commingled with the completion of tanks. Designate Type of Completion Date Spudded	ith that from any other lease or pool on $-(X)$ Gas Well Date Compl. Ready to Prod.	ol, give commingling order number: New Well Workover Deepen Total Depth	Plug Back Same Res'v. Diff. Re
give location of tanks. If this production is commingled with the completion of tanks. Designate Type of Completion Date Spudded	ith that from any other lease or pool on $-(X)$ Gas Well Date Compl. Ready to Prod.	ol, give commingling order number: New Well Workover Deepen Total Depth	Plug Back Same Res'v. Diff. Re
give location of tanks. If this production is commingled with the completion of the	ith that from any other lease or pool on — (X) Date Compl. Ready to Prod. Name of Producing Formation	ol, give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay AND CEMENTING RECORD	Plug Back Same Res'v. Diff. Re P.B.T.D. Tubing Depth Depth Casing Shoe
give location of tanks. If this production is commingled with the completion of the	on — (X) Oil Well Gas Well Oate Compl. Ready to Prod. Name of Producing Formation	ol, give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay	Plug Back Same Res'v. Diff. Re
give location of tanks. If this production is commingled with the completion of the	ith that from any other lease or pool on — (X) Date Compl. Ready to Prod. Name of Producing Formation	ol, give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay AND CEMENTING RECORD	Plug Back Same Restv. Diff. Re
give location of tanks. If this production is commingled with the completion of the	ith that from any other lease or pool on — (X) Date Compl. Ready to Prod. Name of Producing Formation	ol, give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay AND CEMENTING RECORD	Plug Back Same Restv. Diff. Re P.B.T.D. Tubing Depth Depth Casing Shoe
give location of tanks. If this production is commingled with the completion of the	ith that from any other lease or pool on — (X) Date Compl. Ready to Prod. Name of Producing Formation	ol, give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay AND CEMENTING RECORD	Plug Back Same Restv. Diff. Restruction P.B.T.D. Tubing Depth Depth Casing Shoe
give location of tanks. If this production is commingled with the completion of the	Oil Well Gas Well on — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, A CASING & TUBING SIZE	ol, give commingling order number: New Well Workover Deepen	Plug Back Same Restv. Diff. Restruction P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT
give location of tanks. If this production is commingled with the completion of the	Oil Well Gas Well On - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, A CASING & TUBING SIZE	ol, give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay AND CEMENTING RECORD DEPTH SET	Plug Back Same Restv. Diff. Re P.B.T.D. Tubing Depth Depth Casing Shoe
give location of tanks. If this production is commingled with the completion of the	Oil Well Gas Well on — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, A CASING & TUBING SIZE FOR ALLOWABLE (Test must be able for thi	ol, give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay AND CEMENTING RECORD DEPTH SET be after recovery of total volume of load oils of depth or be for full 24 hours)	Plug Back Same Resiv. Diff. Diff. Resiv. Diff. Diff. Resiv. Diff. Diff. Resiv. Diff. Dif
give location of tanks. If this production is commingled with the completion of the	Oil Well Gas Well On - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, A CASING & TUBING SIZE	ol, give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay AND CEMENTING RECORD DEPTH SET	Plug Back Same Resiv. Diff. Re P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT
give location of tanks. If this production is commingled with the completion of the	Oil Well Gas Well on — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, A CASING & TUBING SIZE FOR ALLOWABLE (Test must be able for this	ol, give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay AND CEMENTING RECORD DEPTH SET be after recovery of total volume of load oils of depth or be for full 24 hours)	Plug Back Same Res'v. Diff. Re P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT
give location of tanks. If this production is commingled with the completion of the	Oil Well Gas Well on — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, A CASING & TUBING SIZE FOR ALLOWABLE (Test must be able for thi	ol, give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay AND CEMENTING RECORD DEPTH SET be after recovery of total volume of load oil is depth or be for full 24 hours) Producing Method (Flow, pump, gas leading mathematical producing math	Plug Back Same Resiv. Diff. Re P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top a ift, etc.)
give location of tanks. If this production is commingled with the completion of the	Oil Well Gas Well on — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, A CASING & TUBING SIZE FOR ALLOWABLE (Test must be able for this	ol, give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay AND CEMENTING RECORD DEPTH SET be after recovery of total volume of load oil is depth or be for full 24 hours) Producing Method (Flow, pump, gas leading mathematical producing math	Plug Back Same Res'v. Diff. Re P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top a lift, etc.)
give location of tanks. If this production is commingled with the completion of the	Oil Well Gas Well on - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, A CASING & TUBING SIZE FOR ALLOWABLE (Test must be able for this.) Date of Test Tubing Pressure	ol, give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay AND CEMENTING RECORD DEPTH SET De after recovery of total volume of load oil s depth or be for full 24 hours) Producing Method (Flow, pump, gas leading Pressure	Plug Back Same Res'v. Diff. Re P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top a lift, etc.) Choke Size
give location of tanks. If this production is commingled with the completion of the	Oil Well Gas Well on - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, A CASING & TUBING SIZE FOR ALLOWABLE (Test must be able for this.) Date of Test Tubing Pressure	ol, give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay AND CEMENTING RECORD DEPTH SET De after recovery of total volume of load oil s depth or be for full 24 hours) Producing Method (Flow, pump, gas leading Pressure	Plug Back Same Res'v. Diff. Re P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top a lift, etc.) Choke Size
give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completi Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test	Oil Well Gas Well on - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, A CASING & TUBING SIZE FOR ALLOWABLE (Test must be able for this.) Date of Test Tubing Pressure	ol, give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay AND CEMENTING RECORD DEPTH SET De after recovery of total volume of load oil s depth or be for full 24 hours) Producing Method (Flow, pump, gas leading Pressure	Plug Back Same Res'v. Diff. Re P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top a lift, etc.) Choke Size
give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completi Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test	Oil Well Gas Well on - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, CASING & TUBING SIZE FOR ALLOWABLE (Test must be able for this Date of Test Tubing Pressure Oil-Bbls.	ol, give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay AND CEMENTING RECORD DEPTH SET De after recovery of total volume of load oil s depth or be for full 24 hours) Producing Method (Flow, pump, gas leading Pressure	Plug Back Same Res'v. Diff. Re P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top a lift, etc.) Choke Size
give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completi Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test	Oil Well Gas Well on - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, A CASING & TUBING SIZE FOR ALLOWABLE (Test must be able for this.) Date of Test Tubing Pressure	ol, give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay AND CEMENTING RECORD DEPTH SET be after recovery of total volume of load oil s depth or be for full 24 hours) Producing Method (Flow, pump, gas left) Casing Pressure Water-Bbls.	Plug Back Same Res'v. Diff. Re P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top a lift, etc.) Choke Size Gas-MCF
give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completi Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test	Oil Well Gas Well on - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, CASING & TUBING SIZE FOR ALLOWABLE (Test must be able for this Date of Test Tubing Pressure Oil-Bbls.	ol, give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay AND CEMENTING RECORD DEPTH SET be after recovery of total volume of load oil s depth or be for full 24 hours) Producing Method (Flow, pump, gas left) Casing Pressure Water-Bbls.	Plug Back Same Res'v. Diff. Re P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top a lift, etc.) Choke Size Gas-MCF
GAS WELL Actual Prod. Test-MCF/D (If this production is commingled with the production is commingled with the production of tanks. (If this production is commingled with the production is commingled with the production of tanks. (If this production is commingled with the production of the produc	Oil Well Gas Well on — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, CASING & TUBING SIZE FOR ALLOWABLE (Test must & able for this Date of Test Tubing Pressure Oil-Bbls.	ol, give commingling order number: New Well Workover Deepen	Plug Back Same Res'v. Diff. Re P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top a ift, etc.) Choke Size Gas-MCF Gravity of Condensate Choke Size
GAS WELL Actual Prod. Test-MCF/D (If this production is commingled with the production is commingled with the production of tanks. (If this production is commingled with the production is commingled with the production of tanks. (If this production is commingled with the production of the produc	Oil Well Gas Well Ion — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, A CASING & TUBING SIZE FOR ALLOWABLE (Test must be able for this Date of Test Tubing Pressure Oil-Bbls. Length of Test Tubing Pressure	ol, give commingling order number: New Well Workover Deepen	Plug Back Same Restv. Diff. Restriction P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top of the condition of the condition Gas-MCF Gravity of Condensate Choke Size Choke Size ATION COMMISSION
give location of tanks. If this production is commingled with the production of the complete	Oil Well Gas Well Ion — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, A CASING & TUBING SIZE FOR ALLOWABLE (Test must be able for this Date of Test Tubing Pressure Oil-Bbls. Length of Test Tubing Pressure	ol, give commingling order number: New Well Workover Deepen	Plug Back Same Restv. Diff. R P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top of the company

retornal stanco Bt

Division Superintendent

Nov. 3, 1966

(Signature)

, 19

DIL AND GAS INSPECTOR TITLE _

This form is to be filed in compliance with RULE 1104.

If this is a request for allowable for a newly drilled or deepened well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

All sections of this form must be filled out completely for allowable on new and recompleted wells.

Fill out only Sections I, II, III, and VI for changes of owner, well name or number, or transporter, or other such change of condition.

Separate Forms C-104 must be filed for each pool in multiply completed wells.