Form 9-331a OVEL	N. M. O. C. C. COPM	Budget Buresu No. 42-R358.4. Form Approved.
APPROVE MAN 27 1963 MAN 27 1963 RONNIE E. SHOOK RONNIE E. SHOOK ENGINEER	(SUBMIT IN TRIPLICATE) UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	Land Office Lease No. LUNDDOOL Unit REFETER

SUNDRY NOTICES AND REPORTS ON WELLS

|--|

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

	ay 72, 1963			
Texas Trading Well No. <u>39.</u> is located	1)30 ft.	$\operatorname{from}_{\mathcal{I}, {\boldsymbol{S}}} \left[\begin{array}{c} \mathbf{N} \\ \mathbf{s} \end{array} \right]$ line an	d 120 ft. from $\left\{ \begin{matrix} E \\ \mathbf{W} \end{matrix} \right\}$	line of sec. >>
31/4 X5/4 300. 53	160	51 e	Aura	
(1/2 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	-
Field)	(Co	unty or Subdivision)	斯 会第一章 电压之 S (State or T	

The elevation of the derrick floor above sea level is ______ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We ran 572' 4" liner from 5270-5642 and commented with 100 snoks class "0" comment. Ferforated with erack jets 2 per foot from 5405-15, 3449-54, 3459-63, 3471-77, 3481-95 3585-3615. Total of 134 shots. Spotted 500 gallons 15% regular acid over perforations. Ran 4" packer with 2" tubing and set packer at 5527 with 10,000% tension and connected up for dual injection.

Injection first 24 hours as follows: Lovington 108--2150 Presier 181--1450/

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

 Company
 Service Oil Joapany

 Address
 Sorler Building

 Address
 ORIGINAL SIGNED BY

 Arteria, New Serice
 By

 Title
 Superintendent