

UNITED STATES DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

NEW OIL COMS. CONT. 07  
DRAWER 11  
Artesia, NM 88210

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.  
LC-063368

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIW-TA

2. NAME OF OPERATOR  
Newmont Oil Company

3. ADDRESS OF OPERATOR  
P. O. Box 1305, Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

1980' FSL & 1980' FWL of Sec. 33

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7. UNIT AGREEMENT NAME

Square Lake Flood (East)

8. FARM OR LEASE NAME

Texas Trading

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Square Lake (G. SA)

11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 33-16S-31E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

We propose to plug and abandon the above well as follows:


1. Spot 50 sack cement plug across producing interval in cased hole.
2. Perforate at base of salt 1660', and squeeze with 50 sacks cement leaving 100' plug in casing.
3. Perforate at top of salt 705', and squeeze with 50 sacks cement leaving 100' plug in casing.
4. Set 15 sack cement plug at surface down surface and production casing.
5. Erect permanent well marker.

Note: (a) Your office will be notified 24 hrs. prior to operations.

(b) All plugs will be verified.

(c) Hole will be loaded between all plugs with 10# mud.

(d) We do not plan to pull any casing.



OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*Ernest J. McLaughlin*

TITLE

Area Manager

DATE

7/16/82

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED AS AMENDED

DATE

JUL 20 1982

*James A. Gillham*  
JAMES A. GILLHAM  
DISTRICT SUPERVISOR

\*See Instructions on Reverse Side



# United States Department of the Interior

MINERALS MANAGEMENT SERVICE  
ROSWELL DISTRICT OFFICE  
POST OFFICE DRAWER 1857  
ROSWELL, NEW MEXICO 88201

Re: Permanent Abandonment

Well: No. 5 Texas Trading

## CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases".
2. The Artesia office is to be notified in sufficient time for a representative to witness all plugging operations.

Roswell Office: (505) 624-1790  
Artesia Sub-District: (505) 746-9838  
Hobbs Sub-District: (505) 393-3612

3. Blowout prevention equipment is required.

### 4a. Federal Owned Surface:

- a. ☒ In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e. ripping of pad and/or access road, reseeding, etc. Please contact the Bureau of Land Management for the surface restoration requirements for this well at:

Roswell (505) 622-7670  
Carlsbad (505) 887-6544

- b. ☐ Non-Federal Owned Surface:

Surface restoration after abandonment is to be in accordance with the operator-surface owner agreement. When surface restoration is accomplished, please furnish this office with a statement signed by the surface owner that the restoration is to his satisfaction.