

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

NM OIL CONS. COMMISSION  
SUBMIT IN TR. (Under Instruct) on re-  
Artesia, NM 88210

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> WIW-TA		RECEIVED JUL 22 1982 O. C. D. ARTESIA OFFICE		5. LEASE DESIGNATION AND SERIAL NO. LC-063368	
2. NAME OF OPERATOR Newmont Oil Company ✓				6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 1305, Artesia, New Mexico 88210				7. UNIT AGREEMENT NAME Square Lake Flood (East)	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface  1980' FSL & 660' FFL of Sec. 33				8. FARM OR LEASE NAME Texas Trading	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3978' GLM		9. WELL NO. 6	
				10. FIELD AND POOL, OR WILDCAT Square Lake (G. SA)	
				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 33-16S-31E	
				12. COUNTY OR PARISH Eddy	
				13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

XX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

We propose to plug and abandon the above well as follows:

1. Pull tubing and packer.
2. Spot 50 sack cement plug across producing interval in cased hole.
3. Perforate at base of salt 1735', and squeeze with 50 sacks cement leaving 100' plug in casing.
4. Perforate at top of salt 760', and squeeze with 50 sacks cement leaving 100' plug in casing.
5. Set 15 sack cement plug at surface down surface and production casing.
6. Erect permanent well marker.

Note: (a) Your office will be notified 24 hrs. prior to operations.  
(b) All plugs will be verified.  
(c) Hole will be loaded between all plugs with 10# mud.  
(d) We do not plan to pull any casing.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Manager

DATE

7/16/82

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED AS AMENDED

\*See Instructions on Reverse Side

JUL 20 1982  
JAMES A. GILLHAM  
DISTRICT SUPERVISOR



# United States Department of the Interior

## MINERALS MANAGEMENT SERVICE

ROSWELL DISTRICT OFFICE

POST OFFICE DRAWER 1857

ROSWELL, NEW MEXICO 88201

Re: Permanent Abandonment

Well: No. 6 Texas Trading

### CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases".
2. The Artesia office is to be notified in sufficient time for a representative to witness all plugging operations.

Roswell Office: (505) 624-1790

Artesia Sub-District: (505) 746-9838

Hobbs Sub-District: (505) 393-3612

3. Blowout prevention equipment is required.

#### 4a. Federal Owned Surface:

a. ☒

In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e. ripping of pad and/or access road, reseeding, etc. Please contact the Bureau of Land Management for the surface restoration requirements for this well at:

Roswell (505) 622-7670

Carlsbad (505) 887-6544

b. ☐

#### Non-Federal Owned Surface:

Surface restoration after abandonment is to be in accordance with the operator-surface owner agreement. When surface restoration is accomplished, please furnish this office with a statement signed by the surface owner that the restoration is to his satisfaction.