		Form	9-331		
1	/	+ May	1960 i		

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

SUBMIT IN TRII DEPARTMENT OF THE INTERIOR verse side boosts

	Form approved. Budget Bureau No. 42-Ri						
į	5.	LEASE	DESIGN	ATION	AND	BERI	AL NO

REPAIRING WELL

ALTERING CASING

ABANDON MENT*

Producer

C/SF GEOLOGICAL SURVE	LC-063368		
SUNDRY NOTICES AND REPOR (Do not use this form for proposals to drill or to deepen or use "APPLICATION FOR PERMIT—" for	TS ON WELLS plug back to a deface MEDir. such proposals.)	6. IF INDIAN, ALLOTTI	CE OR TRIBE NAME
1.		7. UNIT AGREEMENT N	
WE'L GAS WELL OTHER WIW SI	FEB 25 1982	Square Lake	Flood East
2. NAME OF OPERATOR		8. FARM OR LEASE NA	ME
Newmont Oil Company '	O. C. D.	Texas Trad	ing
3. ADDRESS OF OPERATOR	ADTESIA OFFICE	9. WELL NO.	
P. O. Box 1305Artesia, New M	ARTESIA, OFFICE Lexico 88210	8	
4. LOCATION OF WELL (Report location clearly and in accordance wit	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*		
See also space 17 below.) At surface		Square Lat	re Grayburg
1270' FNL & 1650' FEL Sec. 33		11. SEC., T., R., M., OR SURVEY OR ARE	BLK. AND San Andr
1270 THE B 1000 TEE Sec. 5			, T16S, R31E
14. PERMIT NO. 15. ELEVATIONS (Show when	ther DF, RT, GR, etc.)	12. COUNTY OR PARIS	H 13. STATE
3983	' GL	Eddy	New Mexico
16. Check Appropriate Box To Indica	ate Nature of Notice, Report, or	Other Data	
NOTICE OF INTENTION TO:	SUBS	EQUENT REPORT OF:	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

Convert

to

2/4/82....Ran 96 jts 2 3/8" EUE 8rd tbg, 2996.58' plus 12' MA & SN.

PULL OR ALTER CASING


MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

2/4/82.....Ran 2" x 1 1/2" x 12' Pump, 117 3/4" sucker rods, 1 - 3/4" x 8' & and 1 - 3/4" x 6' subs, 1 - 1 1/4" x 12' polish rod.

2/8/82.... Well is currently producing 1 bbl oil, and 57 bbls water.



OFF & GAS U.S. GEOLOGICAL SURVEY ROSWELL NEW ARRIVED

		OUT TIE, INDIVI MEXICO
SIGNED Frank TITLE	Area Manager	DATE 2/8/82
APPROVED BY PETER W. CHESTER TITLE CONDITIONS OF APPROVAL, IF ANY: FEB 2 4 1982		DATE
U.S. GEOLOGICAL SURVEY+Se Instruc	tions on Reverse Side	