

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN PLICATE  
(Other instructions on form)  
NM OIL CONS. COMMISSION  
Drawer DDForm approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-065561 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS NM 88210(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> WIW - TA		7. UNIT AGREEMENT NAME Square Lake Flood (Eas.)	
2. NAME OF OPERATOR Newmont Oil Company		8. FARM OR LEASE NAME Carper Fed. A	
3. ADDRESS OF OPERATOR P. O. Box 1305, Artesia, N.M. 88210		9. WELL NO. #1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 660' FEL of Sec. 34		10. FIELD AND POOL, OR WILDCAT Sq. Lake (G. SA)	
14. PERMIT NO.		12. COUNTY OR PARISH	
15. ELEVATIONS (Show whether DF, RT, etc.) O.C.D. ARTESIA, OFFICE		13. STATE	

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

We propose to plug and abandon the above well as follows:

1. Pull tubing and packer.
2. Spot 50 sack cement plug across producing interval in cased hole
3. Perforate at base of salt 1870', squeezed with 50 sacks cement leaving 100' plug in casing.
4. Perforate at top of salt at 875', and squeeze with 50 sacks cement leaving 100' plug in casing.
5. Set 15 sack cement plug at surface down surface and production casing.
6. Erect permanent well marker

Note:

- (a) Your office will be notified 24 hrs. prior to operations.
- (b) All plugs will be verified
- (c) Hole will be loaded between all plugs with 10# mud
- (d) We do not plan to pull any casing.

18. I hereby certify that the foregoing is true and correct.

SIGNED [Signature] TITLE Area Manager DATE 9/2/82

(This space for Federal or State Office use)

APPROVED BY [Signature] TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

FOR

JAMES A. GILHAM  
DISTRICT SUPERVISOR

\*See Instructions on Reverse Side