

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT**

SUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-029438-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Carper Johnson "A"

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson Queen  
Grayburg San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 35, T-16S, R-31E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL  GAS WELL  OTHER

2. NAME OF OPERATOR

MURPHY OPERATING CORPORATION ✓

APR 19 '88

3. ADDRESS OF OPERATOR

P. O. Drawer 2648, Roswell, New Mexico 88202-2648

O. C. D.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface

1980' FNL & 660' FEL, Unit Ltr. H, Sec. 35, T-16S, R-31E

14. PERMIT NO.

15. ELEVATIONS (Show whether DP, RT, GR, etc.)

4090' D.F.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other) shut-in well

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Under 43 CFR 3103.4-2 (no lease expiration problem) Murphy Operating Corporation hereby requests concurrence in permitting the subject lease to be shut-in. Because it is uneconomical to operate these wells until market conditions change and the price of oil rises to the point where it is economical again to operate these leases, we hereby recommend shutting in the lease.

APR 7 12 17 PM '88  
CARE AREA

RECEIVED

I hereby certify that the foregoing is true and correct

SIGNED

*Melinda K. Hickman*  
Melinda K. Hickman

TITLE Production Supervisor

DATE 4/5/88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

SJS

\*See Instructions on Reverse Side