

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

copy to SF
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Water Injection Well	5. LEASE DESIGNATION AND SERIAL NO. LC 029438A
2. NAME OF OPERATOR ARMWOOD LTD. Murphy Minerals Corp. ✓	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Petroleum Building, Tower Suite, Roswell, NM	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2080' FSL and 2080' FWL	8. FARM OR LEASE NAME Carper Johnson A
	9. WELL NO. 3-Y
	10. FIELD AND POOL, OR WILDCAT Grb, Jackson, Queen S.A.
	11. SEC., T., R., M., OR BLK. AND SURVEY OR ABBA Sec. 35, T16S, R31E
14. PERMIT NO.	12. COUNTY OR PARISH 13. STATE
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4050 D.F. O.C.C.	

RECEIVED

OCT 27 1976

10. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data:

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

- 4/14/75 Ran in to 3500' and spot 35 sack plug. Pulled tubing up and spotted mud-gel.
- 4/15/75 Ran 7" B.P. into 2010' and spotted 35' cement.
- 4/16/75 Shot csg. @ 1697' and 1482. Pumped fresh water. Shot csg. @ 1268'. Pull 11 jts.
- 4/17/75 Pulled 31 jts 7". Pulled 8 5/8". Pulled into 3 jts. below surface. Total 1269' of 7".
- 4/18/75 Ran tubing in to 1710' and set 10 sack plug. Set tubing @ 1400' and spotted 10 sack plug. Pulled up to 1210' and set 40 sack plug. Set 50 sack plug @ 800' and @ 200'. Pumped brine-gel between each plug. Set surface plug (25') rigged down. Erected dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent

DATE

7/22/75

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

*See Instructions on Reverse Side

RECEIVED

JUL 28 1975
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO