

## DEPARTMENT OF THE INTERIOR

(Attach instruction  
verse side)

## GEOLOGICAL SURVEY

copy to SF

Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 56302 A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Water Injection Well

2. NAME OF OPERATOR

ARWOOD LTD.

3. ADDRESS OF OPERATOR

Petroleum Building-Tower Suite, Roswell, NM 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

RECEIVED

990' FSL and 1980' FEL

OCT 28 1976

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

O.C.C.

4043 D.F.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Kennedy Johnson A

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Gbr Jackson, Queen S.A.

11. SEC., T., R., M., OR BLM. AND  
SURVEY OR AREA

35-16s-31e

T16S, Sec 35, R31E

12. COUNTY OR PARISH

13. STATE

Eddy

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

4/8/75 Ran tubing to 3700' and pumped 35 sack plug.

4/9/75 Ran wire line and tagged cement @ 3772'. Shot casing @ 2287'  
and 1897'. Ran tubing and spotted 15 sack plug @ 2300' and  
2000'. Shot casing @ 1046'. Laid down 36 jts of 5 1/2" casing.4/11/75 Shot 8 5/8" @ 199'. Laid down 8 jts. 8 5/8" csg. Ran tubing in  
and spotted 35 sack cement plug @ 1200'. Set a 40 sack plug @ 750'  
and a 50 sack plug @ 250'.

4/14/75 Set top plug (25') and rigged down. Erected dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent

DATE

7/22/75

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OR APPROVAL, IF ANY:

TITLE

RECEIVED

JUL 28 1975

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

\*See Instructions on Reverse Side