

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

**RECEIVED**  
NEW MEXICO OIL CONSERVATION COMMISSION  
**MAY 16 1975**

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

**O. C. C.**  
**ARTESIA, OFFICE**

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No.	
7. Unit Agreement Name <b>ROBINSON UNIT</b>	
8. Farm or Lease Name <b>ROBINSON UNIT, TR. 4</b>	
9. Well No. <b>15</b>	
10. Field and Pool, or Wildcat <b>MALJ. GRAYB. S. A.</b>	
12. County <b>EDDY</b>	

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	
2. Name of Operator <b>AZTEC OIL &amp; GAS CO.</b>	
3. Address of Operator <b>P. O. BOX 837, HOBBS, NEW MEXICO 88240</b>	
4. Location of Well UNIT LETTER <b>0</b> <b>660</b> FEET FROM THE <b>SOUTH</b> LINE AND <b>1980</b> FEET FROM THE <b>EAST</b> LINE, SECTION <b>36</b> TOWNSHIP <b>16</b> RANGE <b>31</b> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) <b>4065' GR</b>	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set 4½" BP @ 3700'.
2. Dump 4 ex. cement on top. 4½" cut off.
3. spot 35 ex. plug @ 1450'.
4. Spot 50 ex. plug @ 990'.
5. Spot 50 ex. plug @ 380'.
6. Spot 10 ex. plug @ surface.
7. Install dry-hole marker and clean location.
8. Hole loaded w/mud and all plugs displaced w/mud.

We did not realize this was in Eddy County and notified the commission in Hobbs, as we plugged four other wells at the time.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Chuy Zahr* TITLE AGENT DATE 5/2/75  
APPROVED BY *Edgar Mesinas* TITLE SUPERVISOR, DISTRICT II DATE JUN 20 1975  
CONDITIONS OF APPROVAL, IF ANY: