

NO. OF COPIES RECEIVED	3
DATE RECEIVED	
BY	
FILE	1
DATE	
NAME	
ADDRESS	1

ARTESIA, OFFICE

50. Indicate Type of Lease
State ☒ ☐
51. State Oil & Gas Lease No.
B 161 - 3

SUMMARY NOTICES AND REPORTS ON WELLS

USE THIS FORM TO REPORT ON THE PROPOSED TO DRILL OR TO CEASE OR TO LOG BACK TO A DIFFERENT RESERVOIR, THE PROPOSED LOCATION FOR PERMIT (SEE FORM O-101) FOR SUCH PROPOSAL(S).

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER - X - Water Injection Well

2. Name of Operator
Anadarko Production Company

3. Address of Operator
P. O. Box 67, Loco Hills, New Mexico 88255

4. Location
UNIT NO. 6 1650 FEET FROM THE North LINE AND 2310 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 16S RANGE 31E NMPL.

5. Elevation (Show whether DF, RT, GR, etc.)

6. County
Eddy

7. Unit Agreement Name

8. Name of Lease Name
Brinson State

9. Well No.
3

10. Field and Pool, or Wildcat
Grayburg-Jackson-Q-5A

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REPAIR WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY SHUT-IN ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐ Repair tubing leak	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.

1. Rig up pulling unit.
2. Pull tubing & injection packer.
3. Exchange packer.
4. Hydrotest tubing to 500 psig while running injection packer back in hole.
5. Set packer & pressure test casing to 500 psig.
6. Inject packer & circulate chemical water (packer fluid) behind tubing.
7. Return well to injection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Area Supervisor DATE April 12, 1982

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE APR 13 1982

CONDITIONS OF APPROVAL, IF ANY: