May 9, 1966

Waterflood Associates Inc., 4505 Republic National Bank Tower Dallas, Texas

Re: Shut-in Well

Gentlemen:

We note from recent production reports that the subject well has not been producing. Therefore, unless notified otherwise by Form C-127, the well involved will receive no allowable beginning June, 1966.

Grayburg Jackson Pool
Brinson State #1-C, 36-16-31

Very truly yours,

Oil Conservation Commission

R. L. Stamets Geologist

RLS/jw

Mer ? rsk

Weterüloon hisochater Inc. 4505 Republic Barionel Bank Bower Dallas, Texas

Mos ad-to the John

Gentieser:

We note Town recent production reports the subject well has not rest producing. Therefore, unless notified otherwise by Para C-127, the wall revolved will recaive no rillowable backedus; Jone 1966.

Stayburg Jerkean Pool Briraon Stauc 41-C 3-18-18-11

Very utuly yours

041 Consouvant a Commission

Standards (1997) Galabota 60

w+\2.59